



Drawbar Inspection and Adjustment Procedure for Motor Grader 16M3/16

**Maintenance and
Repair**

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

Drawbar Inspection and Adjustment Procedure for Motor Grader 16M3/16.....	1
1.0 Introduction.....	2
2.0 Best Practice Description	2
3.0 Implementation Steps.....	3
4.0 Benefits	4
5.0 Resources Required.....	4
6.0 Supporting Attachments / References	4
7.0 Related Best Practices	4
8.0 Acknowledgements	4

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

February 2023
1.04-230222-1

1.0 Introduction

In order to improve adjustment history of table/circle assembly, an inspection and adjustment procedure was created.

After some circle drive failures, it was identified that it was not evident if the assembly had been adjusted and, if so, by whom.

2.0 Best Practice Description

After an occurrence of a fracture in the circle drive, it was observed some of the circle fixing shoes were out of specification.

Since the mentioned episode, a standard inspection document was created with the QR code of the procedure for table/circle assembly and the circle drive adjustment.

By using the phone to read the QR code, technicians may have access to the procedure for table/circle assembly adjustment in SIS and/or access to the video on channel 1, which shows how the procedure should be performed.

During the service, the technician fills out a header about the equipment's data, found/adjusted values, and activity's technician identification aiming to create a maintenance history document (Image 1) of the table/circle set, allowing a better control of the implement's maintenance activities.



TECHICAL REPORT

Customer	VALE S/A - CONCEIÇÃO MINE		
Model	16	Serial Number Prefix:	Serial Number:
Tag	Data		Service Meter:
Technician		Work Order:	



Ajuste de pré-carga do redutor



ajuste caixa de giro.pdf



Ajuste do conjunto de mesa



Video explicativo ajuste do drawbar





ajuste do drawbar.pdf

Image 1 - Technical Report

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Drawbar Inspection and Adjustment Procedure for Motor Grader 16M3/16	DATE 2/22/2023	CHG NO 00	NUMBER 1.04-230222-1

3.0 Implementation Steps

A pilot project was tested during preventive maintenance, focusing on validating the use of the described procedure as images 2, 3, 4 and 5 illustrates:



Images 2 and 3 - Procedure instructions containing parts identification, specification measurements and a blank space to fill with the found measure




Image 4 - Identification and blank filling spaces table




Image 5 - Example of filled table

3.1 Test and Monitor the Solution:

After table/circle assembly inspection and adjustment report implementation, it was no longer observed new occurrences of assembly failure, thus evidencing the efficiency of the developed procedure.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Drawbar Inspection and Adjustment Procedure for Motor Grader 16M3/16		DATE 2/22/2023	CHG NO 00
			NUMBER 1.04-230222-1

4.0 Benefits

- Adjustment history
- Process improvement
- Premature failures avoidance
- Reduction on adjustment time/downtime
- Reduction on rework and/or warranty claim costs

5.0 Resources Required

N/A

6.0 Supporting Attachments / References

SEBU9228-17- i07192342
UENR6762-06 - i06147741 (steps 25 to 30)

7.0 Related Best Practices

N/A

8.0 Acknowledgements

This Best Practice was written by:

Glauber Soares

Sotreq S/A - Mining Engineering
E-mail: glauber.soares@sotreq.com.br

This Best Practice was co-written and implemented by:

Fernando Laguardia

Sotreq S/A - Mining Engineering Consultant
E-mail: fernando.laguardia@sotreq.com.br

Lázara Fonseca

Sotreq S/A - Mining Engineering Consultant
E-mail: lazara.fonseca@sotreq.com.br

Luis Gustavo Rocha

Sotreq S/A - Engineering Coordinator
E-mail: luis.gustavo@sotreq.com.br

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Drawbar Inspection and Adjustment Procedure for Motor Grader 16M3/16	DATE 2/22/2023	CHG NO 00	NUMBER 1.04-230222-1