Jeide, Matthew 4/6/26 Period 2

W14B: CIM [Initials] CNC Motion2.0 Fusion & G&M Code

1. Fusion 360 Design

Insert a Fusion360 screenshot of your 3.25x2x1 block with Personal initials.



2. Fusion 360 Design and Tool Path

Insert a Fusion360 screenshot of your 3.25x2x1 block with initials and the tool path.



3. CNC Motion and GM Code.

Jeide, Matthew 4/6/26 Period 2

W14B: CIM [Initials] CNC Motion2.0 Fusion & G&M Code

CNC Motion and GM Code.
https://m-jeide.github.io/eng-portfolio/resources/CIM/Project/CNC%20Mill/Initials%20G-Code.pdf#zoom=page-width

4. All the above components are in your E-Portfolio.

E-Portfolio: Fusion 360 Design, Fusion 360 Tool Path, & CNC Motion Simulation, and GM Code.
https://m-jeide.github.io/eng-portfolio/CIM/CNC%20Mill