



1. Solvent Clean



2. Photolithography



2. Sulfur Passivation





Single coat, AZ5214

Single coat, AZ5214

Single coat, AZ5214



No Milling



3. Surface Treatment



4. Niobium Sputtering


Room Temperature



5. Liftoff



1. Solvent Clean



2. Photolithography

Negative Liftoff Pattern



Single coat, AZ5214



No Milling




Single coat, AZ5214



3. Surface Treatment



Single coat, AZ5214



Single coat, AZ5214



4. Niobium Sputtering

Room Temperature



Single coat, AZ5214



Single coat, AZ5214



5. Liftoff



Single coat, AZ5214



Single coat, AZ5214

Sulfur Passivation



Single coat, AZ5214



Single coat, AZ5214



Single coat, AZ5214