


Photolithography in six solid states: the openings are trenches across the die, not isolated holes




1 deposition




2 resist coating




3 exposure



4 development



5 film etch



6 resist removal

Mask, light and ions are annotations. The beams are Scene.cone() in the reserved beam color.