

A

B

C


D

A

B

C

D



A

A

B



B


C

C

D


D





A

A



MODE	OE	S1	S0	Switches	Phases
RX	0	0	0	1B1	270
RX	0	0	1	2B2	0
RX	0	1	1	1B4	90
RX	0	1	0	2B3	180
TX	1	X	X	All Open	

