Basic Soldering Workshop PTH and large pitch SMT

Ethan Harstad Ian McInerney

Make to Innovate
Dept. of Aerospace Engineering
Iowa State University

28 September 2013

- Safety
 - Hazards
 - Personal Protective Equipment
 - Safety Procedures
- Basic Procedure
 - Tip/Temperature Selection
 - Joint Preparation
 - Tip Preparation
 - Soldering
 - Troubleshooting
- 3 Example Cases
 - Wire to Pin
 - Wire to Wire
 - Plated Through Hole
- 4 Surface Mount Soldering



Personal Protective Equipment Safety Procedures

Hazard - Burns

Personal Protective Equipment Safety Procedures

Hazard - Lead Exposure

Hazard - Fumes

Personal Protective Equipment Safety Procedures

Hazard - Skin Irritation

Personal Protective Equipment Safety Procedures

Hazard - Electrocution

Personal Protective Equipment

Safety Procedures

- Safety
 - Hazards
 - Personal Protective Equipment
 - Safety Procedures
- Basic Procedure
 - Tip/Temperature Selection
 - Joint Preparation
 - Tip Preparation
 - Soldering
 - Troubleshooting
- 3 Example Cases
 - Wire to Pin
 - Wire to Wire
 - Plated Through Hole
- 4 Surface Mount Soldering



Tip/Temperature Selection

Joint Preparation

Tip/Temperature Selection Joint Preparation Tip Preparation Soldering Troubleshooting

Tip Preparation

Tip/Temperature Selection Joint Preparation Tip Preparation Soldering Troubleshooting

Soldering

Troubleshooting

- Safety
 - Hazards
 - Personal Protective Equipment
 - Safety Procedures
- 2 Basic Procedure
 - Tip/Temperature Selection
 - Joint Preparation
 - Tip Preparation
 - Soldering
 - Troubleshooting
- 3 Example Cases
 - Wire to Pin
 - Wire to Wire
 - Plated Through Hole
- 4 Surface Mount Soldering



Wire to Pin

Wire to Wire

Plated Through Hole

- Safety
 - Hazards
 - Personal Protective Equipment
 - Safety Procedures
- Basic Procedure
 - Tip/Temperature Selection
 - Joint Preparation
 - Tip Preparation
 - Soldering
 - Troubleshooting
- Example Cases
 - Wire to Pin
 - Wire to Wire
 - Plated Through Hole
- Surface Mount Soldering

