POST MORTEM

System Name : TMT01

Customer : ON Semiconductor – TARLAC

Participants : Henry Planada / Hectril Teodosio/Nico Lubo/Arnel Farro

Report Created by : Hectril Teodosio

Issue Reported by : Hectril Teodosio

Report Creation Date: 17.09.16

Problem / Issue(s):

Handler – Tester Communication Problem

17.09.05 (Arnel/Hectril)

> Problem: No Communication between Handler/Tester

> Problem: Cannot execute Manual Testing

Isolations:

- ➤ Replace Interface Cable no response between Handler/Tester
- ➤ Swap Interface Cable from known good setup same
- ➤ Swap workstation from known good setup same
- ➤ Check pin to pin configuration base on communication pins config with recommendation with Sir Mark no response
- ➤ Check SOT pin for 5vs no measurement but measured 5v on EOT pins

17.09.14 – Workstation (CPU) Loaner from CARMONA for TMT1 unable to Boot UP (Arnel/Nico)

Isolations

- Install newly arrived loaner Workstation from CARMONA
- Unable to Boot up
- ➤ Re-insert board modules same

17.09.15 - Handler-Tester Communication Problem / Workstation Loaner from Carmona (Henry/Hectril)

Isolations

- ➤ Load device program and manual test using Handler no response.. unable to test
- Use Workstatiion from Carmona.. unable to boot up
- Check Power Supply of Workstation.. see powersupply is 220V. Setup is plug to 110 Electrical outlet


Problem: Workstation (CPU) Loaner from CARMONA for TMT1 unable to Boot UP RootCause: Low Electrical Voltage causing CPU unable to Boot UP

Problem: Handler – Tester Communication Problem

Isolations:

- Use original Workstation
- ➤ Check Interface cable and use DMM and check for Pin to Ground ok
- Connect Interface cable and reload program no communication on Handler/Tester
- > Run Simulation using Handler Config encounter system crash during simulation
- ➤ Re-install VISUAL ATE SOFTWARE c/o Sir Henry Ok
- Perform simulation no system crash during this activity. Handler and Tester able to communicate

RootCause: Corrupted VISUAL ATE SOFTWARE



- ➤ Use reject units for verification confirm Handler/Tester able to communicate
- Release for Setup and Production

17.09.15

15-Sep- 2017 2028 NS XFN_TST_TIMT001 ASL1000 HDL- SRM008 Z248 RUNNNG PRODUCTION M1-Operational A67 TRME- ASSY BEUBG330009H 849.08 4 4 0 0 M/les Eliazar.Lacs on									HEED HORITONING									
	2017 20:28	NS	XFN_TST_TMT001	ASL1000	XFN- HDL- SRM008	/ /4X	RUNNING PRODUCTION	PRODUCTION	M1-Operational	40/	1410010- TRME- ASSY	BEUBG330009H	849.06	4	4	0	0	Myles Eliazar, Lacs on

17.09.16

16-Sep- 2017 13:38	XFN_TST_TMT001 XFN+DL- SRM008	1410010-TRM-E-ASSY	XDFN	BELBG330009H	25	25	4	4	3.9 0.34	RUNNING PRODUCTION	PRODUCTION	.28	1ST REEL FOR BY OFF_(ENCOUNTER POOR SEALING)	Liezel.Ounanan	<u>Select</u>	
-----------------------	----------------------------------	--------------------	------	--------------	----	----	---	---	----------	-----------------------	------------	-----	--	----------------	---------------	--