








- H1 MountingHole
- H2 MountingHole
- H3 MountingHole
- H4 MountingHole



Cutoff Q2 pulls Q3 up
PMOS blocks battery discharge
Button trigger activates Q2
Q3 saturates, V_REG = V_BAT - 200mV
Supermini boots, drive GPIO4 high to latch power on

Power-on latch and button



Restricted pins: 6, 7, 8, 11, 16, 17
Strap pins: 0, 2, 5, MTDI, MTDO
Input only: 34, 35, 36, 37, 38, 39

