



G01 X44 Y48 G02 X47 Y45 R3 G01 X47 Y8.25 G01 X41.75 Y3 G01 X6 Y3 G02 X2 Y7 R4 G01 X2 Y25 G01 G40 X-20 Y25 M99 N20 G91 G01 Z-0.2 G90 G01 G42 X15 Y25 F300 D01 G01 X15 Y29 G02 X21 Y35 R6 G01 X25 Y35 G02 X25 Y15 R10 G01 X21 Y15 G02 X15 Y21 R6

G01 X15 Y25

M99

G01 G40 X25 Y25