Marine & Ports ZA

FIELD SERVICE TIMESHEETS

Customer reference: PO727/3010052693	**ABB Reference:** 4202788236	**Date:** 09 December 2025
Vessel Name: Bourbon Explorer 517	**Flag / IMO No**: France / 9654323	**MMSI No:** 228064800
Customer: Bourbon Offshore Surf		**Ticket No:**
Location: Walvis Bay, Namibia		
Attending Engineer/s: Lenos Machiridza		
Customer Contact Person: Francois DEBERGUES - PMP Project Manager		
Address: 50, rue de Forbin - CS 60703 - 13235 Marseille Cedex 02		
e-mail: Francois.DEBERGUES@bourbon-online.com	**cell.:** +33 (0)7 85 77 70 44	

Case description / history:

- ABB to perform Configuring and Parameterizing ACS880Drive for Fan No.3

EQUIPMENT DETAILS - SERIAL NUMBER/S:

- Fan No.3 Drive Model: ACS880-01-040-B056(512)
- Drive serial number: 1225003518
- Firmware Version: AINF6 v3 42

BOURBON EXPLORER 517
PSV - DP2
Reg. Marseille 3147 G
IMO 9654323 5140 K

Friday, 05th November 2025	**OFFSHORE:**	**ALONGSIDE:**
Time Start: **Time Finish:**	**Travel time**: 09:00 to 17:00 • Preparation and travel from Pretoria to JHB to Walvis Bay to Hotel. **Description:** **Working time:**	
Saturday, 06th December 2025	**OFFSHORE:**	**ALONGSIDE:**
Time Start: **Time Finish:** **(Fixed Day Rate)**	**Travel time**: • N/A **Description:** **Working time:** • Permit to work, LOTO, Toolbox talks etc. • Drive parameter backups Fan No 3, ACS880 Drive. • Drive configuration and setting of parameters • Daily logs and reports.	
Sunday, 07th December 2025	**OFFSHORE:**	**ALONGSIDE:**
Time Start: **Time Finish:** **(Fixed Day Rate)**	**Travel time**: • N/A **Description:** **Working time:** • Permit to work, LOTO, Toolbox talks etc. • Continued with fault finding as to why ECR display is not changing to remote, when remote is selected on the drive. • Daily logs and reports	
Monday, 08th December 2025	**OFFSHORE**	**ALONGSIDE:**
Time Start: **Time Finish:** **(Fixed Day Rate)**	**Travel time**: **Description:** Travel from Walvis Bay to Johannesburg to Pretoria **Working time:** • Permit to work, LOTO, Toolbox talks etc. • Continued with fault finding as to why ECR display is not changing to remote, when remote is selected on the drive. • Problem resolved, fan can now be started from ECR • Daily logs and reports	
Tuesday, 09th December 2025	**OFFSHORE**	**ALONGSIDE:**
Time Start: **Time Finish:**	**Travel time**:	

BOURBON EXPLORER
PSV - DP2
Reg. Marseille 314
IMO 9654323 54

(Fixed Day Rate)	**Description:** Travel from Walvis Bay to Johannesburg to Pretoria **Working time:**

Attendance Summary:

- ABB to parameterize and configure ACS880 Drive for Fan3 to be started remotely.

NB:All travel and mobilization times will be added accordingly

Responsible Person/s	
ABB Service Engineer: Lenos Machiridza	**Signature:**
Customer Rep. Name: Antoine Une Sae **Title :** master	**Signature:**
Date: 07 December 2025	

Customer Signature

BOURBON EXPLORER 51
PSV - DP2
Reg. Marseille 3147 G
IMO 9654323 5440

Customer Stamp