# How to enter Debug tool

1. Power on EXC200 firstly**.**
2. In login interface, click **Ctrl+Alt+F8** together. (Nothing will be changed after this clicking, please continue the following steps.)


3. Click **Ctrl+Alt+Del** together to enter function interface.

4. Click Task Manager, then you will find task manager menu as the following picture.
   PS: if you can not see full menu of task manager, click left down "More details" to find full menu.

Floor 1 to Floor 4, Building 30, No.6 of Taikang Road,
Block C of Jianqiao Industrial Park, Dadukou District, Chongqing, China 400082
Tel: +86 (0)23 6865 5509   Fax: +86 (0)23 6869 9779   Email: info@zybio.com   Website: www.zybio.com

5. Click **File** => **Run new task** in the top left corner of Task Manager.

6. Input **"explorer.exe"** into the pop-up dialog box, and click **OK**.

7. Enter "desktop", then tap the EXC200 Debugtool, then choose the English language, tap ok.

Floor 1 to Floor 4, Building 30, No.6 of Taikang Road,
Block C of Jianqiao Industrial Park, Dadukou District, Chongqing, China 400082
Tel: +86 (0)23 6865 5509   Fax: +86 (0)23 6869 9779   Email: info@zybio.com   Website: www.zybio.com

8. Click [Debugging Ass.]➔[connect]➔[Whole unit Reset] first! Must reset the machine before doing position adjustment!

Floor 1 to Floor 4, Building 30, No.6 of Taikang Road,
Block C of Jianqiao Industrial Park, Dadukou District, Chongqing, China 400082
Tel: +86 (0)23 6865 5509   Fax: +86 (0)23 6869 9779   Email: info@zybio.com   Website: www.zybio.com