
Opis	AX pin	MEGA pin	
A – step	28	4	
A – dir	27	5	
B – step	3	6	
B – dir	2	7	
C – step	14	8	
C – dir	13	9	
Reset	26	10	



Motor pin	AX pin	Motor pin	AX pin	Motor pin	AX pin
M1-1	OUT1C - 21	M2 – 1	OUT1B - 22	M3 – 1	OUT1A - 7
M1 – 2	OUT2C - 20	M2 – 2	OUT2B – 23	M3 – 2	OUT2A – 6
M1-3	OUT3C – 18	M2 – 3	OUT3B – 25	M3 – 3	OUT3A – 4
M1-4	OUT4C – 19	M2 – 4	OUT4B – 24	M3 – 4	OUT4A – 5