# **SHAMS POWER COMPANY**

### **ENGINEERING DIVISION**

# **INSPECTION & CORROSION SECTION**

# SHAMS 1

**LOCATION: R1MAG10AH001** 

#### KKS:

- 1- R1MAG10AH001 (AIR COOLER)
- 2- R1MAG10BZ001 (EXPANSION BELLOW)
- 3- R1MAG10BZ002 (EXPANSION BELLOW)
- 4- R1MAG10BZ003 (EXPANSION BELLOW)

# **CERTIFICATE OF INSPECTION**

The equipment detailed below was examined in accordance with the SHAMS code of practice for plant inspection,

ITEM: Air cooler 10 Location: SHAMS Plant

Type of Inspection: Major Date of Inspection: March, 2020

Place of Inspection: IN-SITU Date of Last Inspection: Jan, 2019

#### **REPORT:**

#### 1.0. Summary

The above air cooler was taken off line, isolated, opened, vented & cleaned for major external & internal inspections.

# 2.0. Subject

2.1. This is a horizontal air tube connected to incline fined tubes receiving water vapor from turbine through 20 "pipe protected by three expansion joint.

Size	
Design pressure	0.49 bar
Design temperature	460 c
Operation pressure	0.3bara
Operation temperature	100c
Fluid characteristics @ 141 c	Steam- condensate

.....

#### -----

The above equipment is/ is not considered suitable for further service under the present operating conditions

Next Major Inspection Due: Jan. 2024 Inspected: Osman Ismail

Reviewed: Ali Al Masabai Endorsement: 48 Months

### 3.0 History

This air cooler was commissioned in 2013. Periodical inspection records since Oct.'2014 are available.

# 4.0. Scope of Inspection

- 4.1 Visual inspection.
- 4.2 Ultrasonic thickness measurement.
- 5.2 Dye –penetrant

#### 5.0. Conditions Found

#### 5.1. External -

- 5.1.1 All painting surfaces found intact without any evidence of peel off for external surfaces.
- 5.1.2 All three attached expansion bellows found satisfactory with no evidence of cracks or mechanical damage.
- 5.1.3 All aluminum fins found clean and in satisfactory condition with no evidence of any deposits or mechanical damaged.
- 5.1.4 Water dust blower found in satisfactory condition.
- 5.1.5 All ladders, stairways and handrails found in satisfactory condition.
- 5.1.6 All concrete support found in satisfactory condition without evidence of cracking or spalling.
- 5.1.8 Manhole found in satisfactory condition without evidence of any corrosion.
- 5.1.9 All external piping insulation found in satisfactory condition.
- 5.1.10 All earthling lugs found in satisfactory condition.

#### 5.2. Internal -

- 5.2.1 All internals found in satisfactory condition without evidence of fallen down, damage or corrosion.
- 5.2.2 All internal surfaces of shell and heads found in satisfactory condition, apart from normal carbon steel very thin hydroxide layer.
- 5.2.3 All welds of shell and heads found in satisfactory condition without evidence of heavy corrosion
- 5.2.4 All internal surfaces of connected nozzles and manway found in satisfactory condition without evidence of sever corrosion.
- 5.2.5 All thermos wells found in satisfactory condition.

#### 5.8.1. Ultrasonic Testing

Ultrasonic thickness measurement was carried out on the internal pipe surfaces and heads found satisfactory. See attached thickness measurement report.

### 6.0. Recommendations

It is recommended to open air cooler after 4 years as per SHAMS Code of Practice.

#### 10. Inspection Grade and Interval


In accordance with the latest revision of SHAMS Code of Practice, this **air cooler was** endorsed for 48 months for next Major Inspection.


Frequency : 48 Months.
Endorsement : 48 Months
Next Moior Inch.

Next Major Insp. due : January 2024

# **Photos**









International Inspection Services Ltd.

NON DESTRUCTIVE TESTING/HEAT TREATMENT/ADVANCED INSPECTION SERVICES, CALIBRATION SERVICES AND MECHANICAL & METALLURGICAL LAB SERVICES

intertek.com

Form No.: IN-QSF-36 Rev. 05E Dtd.: 20-10-2018

		ULT					EXCESS OF MANY RESULTS AND SECURISHES AND SECURISHES.		
Client:	SHAMS POWER C	OMPANY	WHEN THE REPORT OF THE PARTY HER THE PARTY HER TO SEE THE PARTY HE PARTY HER TO SEE THE PARTY		and the state of the second state of the secon	unes prinsi i indicata di indi			
Date:		06.03.2020	-	Report No.:		AD / 466			
Project:		SHAMS OUTAGE MAR	RCH 2020			N/A			
ocation:	: MADINAT ZAYED		YED	Drawing No.:		N/A			
em ID:	m ID: ACC BLOWER		ER .	Material:	***************************************	CS			
ef/ Proc	/ Procedure No: INSPEC/UTG/001 R		5/001 Rev.10	Ref. Standard:		ASME SEC V			
TG Equi	pment Model/		X DAC / GE	Serial No.:		7292a			
lanufaci alibratio	turer: on Block No. :		E, IIW V2 BLOCK		n Certificate &	Certificate & Due			
obe Ty		MAY YOUR BEAUTIFUL TO SHEET THE STATE OF THE	NK TR 0° PROBE/ 10mm DIA / 5 MHz		Name & Type		INS/UT/CAL-043/19/AUH		
ze/Freq onnectir	uency: ng Cable Type &			Special Attachm					
ength:			CRODOT & 2 MTR	Equipment/ Block:		STEP WEDGE BLOCK (SL N			
	perature:	AM	<b>IBIENT</b>	Surface Condition	on:	AS CLEANED			
spectio	n Date:	06.0	03.2020	Page: 1	of		3		
OR THI	CKNESS DETAILS RI	EFER CONTINUATION SHI	EET						
FOR THI	CKNESS DETAILS RI	EFER CONTINUATION SHI	EET						
FOR THI		REP		ABLE ONLY FOR AUH & F	FUJ FACILITY				
	LEVEL II TEC	REP	ORT FORMAT APPLICA	ABLE ONLY FOR AUH & F			AI / TPI		
me:	LEVEL II TEC	REP	ORT FORMAT APPLICA CLIEN Name:		Na	ame :	Al / TPI		
FOR THI	LEVEL II TEC	REP	ORT FORMAT APPLICA		N: Si	ame: gn: ate:	Al / TPI		



International Inspection Services Ltd.

NON DESTRUCTIVE TESTING/HEAT TREATMENT/ADVANCED INSPECTION SERVICES, CALIBRATION SERVICES AND MECHANICAL & METALLURGICAL LAB SERVICES

intertek.com

Form No.: IN-QSF-36A Rev. 05E Dtd.: 20-10-2018

		LITTRACONICT	HICKNIECC CC	ARIAHAIC DEDO	ST.	HARMONIA CONTRACTOR		
		ULTRASONIC T	ONTINUATION SE		RI			
ate:	06.03.2020	Report No.:		D- 466	Page:	2	Of	3
LOCATION	ORIENTATION	ORIGINAL THICKNESS	MEASURED THICKNESS	DIMINUTION IN	DIMINUTION IN		REMARK	
1	-		MINIMUM (mm) 16.29	mm -	%	A GERMAN		
1	-	-	16.14	-				
1	-		16.03		-		-	
1	-		15.98		-	-	-	
1	-	_	16.21		-		-	
2		_	15.68		-			
2			15.79		-			
2			16.00	-	-		-	
2	_		15.88	-	-		-	
2					-	************		o let comprehense to comprehense
2			15.93		-		-	VERTICAL AND AN ANALYSIS OF
3		-	15.92	-	-		-	
3			20.29	-	-	***************************************	-	
3	-	-	20.32	-	-		-	
3		-	20.31	-				******
		-	20.13	-	-		-	
3		-	20.14	-	-		-	~~~
3		-	20.19	-	-		-	
4	-		20.02	-	-		-	
4	-		20.21	_	-	7/17/24/4	-	
4	•	-	20.32	-	-	· more very service and	-	
4		-	20.13		-	-		
4	-	-	20.14	-	-		-	
4		-	20.17	-	-		-	
4		-	20.19	_	-		-	
5		-	20.20	-	-		-	Ne title i varia paintine i i i i
5	-	-	19.73	-	-	······································	-	
5		-	20.01	-	-		-	
5	=	-	19.78	-	-	rakinik rakiningay oʻray ilan mil anki ilaki an yayu asu	-	
5	-	-	19.73	-	-	***************************************	-	
5	-	-	19.43	-	-		-	
5	-		20.12	-	-		-	
6	-	-	15.83	-	-		-	
6	-	-	15.87		-		-	***************************************
6	-		16.01	-	-	THE STATE OF THE S		WYTEN METERS OF THE PERSON NAMED IN COLUMN TO THE PERSON NAMED IN
6	-	-	15.97	_	-		-	
6	-	-	15.88	-			-	
		REPORT FORMAT	APPLICABLE ONLY FO	R AUH & FUJ FACILITY				
	LEVEL II TECH	HNICIAN	CLIEI	NT REP.		AI/TPI		
me :	SHYMAL I	AULE	Name :		Name :			toron account
n:	Level II No.		Sign :		Sign:			
	660 05.03.20 O Box: 96535, Uubai, O.A.E	020 :	Date : Fax: 04 3241957	Email: Income dub.	Date :		***************************************	
	U Box: 6130, Sharjan, U.A.E		Fax: 06 5361173	Email: Inspec.dxbcoor@intertek.com Email: Inspec.shjcoor@intertek.com			INSPEC IS PART	OF INTERTE
habi Branch : P	O Box: 41227, Abu Uhabi, U.A.E O Box: 7907, Fujairah, U.A.E	Tel: 02 6225820	Fax: 02 6225830 Fax: 09 2238754	Email: Inspec.adhcoor@intertek.com				



# International Inspection Services Ltd. NON DESTRUCTIVE TESTING/HEAT TREATMENT/ADVANCED INSPECTION SERVICES, CALIBRATION SERVICES AND MECHANICAL & METALLURGICAL LAB SERVICES

intertek.com

Form No.: IN-QSF-36A Rev. 05E Dtd.: 20-10-2018

		ULTRASONIC T	ONTINUATION SHE					
ate:	06.03.2020	Report No.:	AD-		Page:	3	Of	3
LOCATION	ORIENTATION	ORIGINAL THICKNESS	MEASURED THICKNESS MINIMUM (mm)	DIMINUTION IN mm	DIMINUTION IN %		REMARK	
6	-	ACCOUNTY AND THE PROPERTY OF T	15.89		-			
6	-	-	16.20	-	*		-	
7	-	-	15.98	-	-			
7	-	-	15.86	-	-	***************************************	-	
7	-	-	15.87	-	-		-	
7	-	-	15.99	-	-		~	
7	-	-	15.88	-	-	***************************************	-	
8	-	-	20.93	-	-		-	
8	-	-	20.94	-	-		-	
8	-	-	20.99	-	-			
8		-	21.05	-	-		-	
8	-	-	21.05	-	-		-	
8	-	-	21.21	=	-			
9	-	-	20.78	-	-		-	
9	-	-	20.93	_	-		-	
9	-	-	20.24		-	***************************************	-	
9	-	-	20.39	-	-		-	
9		-	2.43	-	-		-	
10		-	20.73	-	-		-	and the second
10		-	20.73	-	-		-	
10		-	29.30	-	-		-	
10		-	29.50	-	-		=	
10		•	29.60	-	-		-	
		Management of the state of the						
							***************************************	TO TAKE THE PARTY OF THE PARTY
		DEDOOT FORM	DDIIGADIS					
	15/51 115-6	от в бранический принципальной делений принципальной и принципальной принципальной и принципальной и принципал	APPLICABLE ONLY FOR					
LEVEL II TECHNICIAN ame: SHYMAL PAUL			CLIEN1	REP.		AI/TPI		
n:		The state of the s	Name : Sign :		Name :			
te :	O BOX 903 S, DUDA, JALE NOS. 0312	020	Date :		Sign: Date:			
i Branch : P	U BOX: 905 5, DUDA, O.A.E. NO.	Tel: 04 3241955 . Tel: 06 5361300	ax: 04 3241957 E	mail: Inspec.dxbcoor@intertek.com mail: Inspec.shjcoor@intertek.com			INSPEC IS PART (	OF INTERTEK

## U 860: 1935, Nation Out. | Tal-eff-3241955 |
## U 860: 1935, Nation Out. | Dale | Tel: 06: 5361300 |
## U 860: 41-47, ABU U man, U.A.E | Dale | Tel: 06: 25820 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 2238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: 238754 |
## U 860: 193, P.C. 131, Sultanate or Uman | Tel: 00: Sharjah Branch Abu Dhabi Branch Fujairah Branch Oman Branch Registered Office Fax: 04 3241957 Fax: 06 5361173 Fax: 02 6225830 Fax: 09 2238754 Fax: 00968 2448 5855 Email: Inspec.dxbcoor@intertek.com Email: Inspec.shlcoor@intertek.com Email: Inspec.adhcoor@intertek.com Email: Inspec.fujcoor@intertek.com Email: Inspec.muscat@intertek.com For Complaints & Suggestions: Please email to:suggestions.inspec@intertek.com

★ UTG LOCATION ACC SIDE Report No.:- AD-466 **Date:** 06.03.2020 Page No. :- 2 OF 2 \$ ₹ ULTRASONIC THICKNESS SCANNING DRAWING SHEET International Inspection Services Ltd \* ACC BLOWER Intertek.com intertek inspec Name 650 AFZ Sale ANSARI Date: 06.03.2020 **TURBINE SIDE**