SHAMS POWER COMPANY

ENGINEERING DIVISION

INSPECTION & CORROSION SECTION

SHAMS 1

LOCATION: R1LAA10BB001

KKS: R1LAA10BB001

CERTIFICATE OF INSPECTION

The equipment detailed below was examined in accordance with the SHAMS code of practice for plant inspection,

ITEM: Deaerator and feed water tank LOCATION: SHAMS Plant

TYPE OF INSPECTION: Major DATE OF INSPECTION: March, 2020

PLACE OF INSPECTION: IN-SITU DATE OF LAST INSPECTION: Jan, 2019

REPORT:

1.0. Summary

The above pressure vessel was taken off line, isolated, opened, vented & cleaned for major external & internal inspections.

2.0. Subject

2.1. This is a horizontal, cylindrical, ASTM A-516 Gr.70 tank with one inlet and outlet of boiler feed water, inlet of bleed 3 steam turbine, gases outlet and inlets of chemical dosing.

Size	Length 10.5m X internal diameter 3.4m
Design pressure	5.6 bara
Design temperature	180c
Operation pressure	3.7 bara
Operation temperature	141c
Fluid characteristics @ 141 c	Water density: 925,2 kg/m3 viscosity: 0,14
	mPa.s
Shell minimum thickness	15+3mm corrosion allowance
Head minimum thickness	12.75+3mm corrosion allowance

The above equipment is/ is not considered suitable for further service under the present operating conditions

Next Major Inspection Due : January 2024 Inspected: Osman Ismail

Endorsement: 48 Months

Reviewed: Ali Al Masabai

3.0 History

This tank was commissioned in 2013. Periodical inspection records since Oct.'2014 are available.

4.0. Scope of Inspection

- 4.1 Visual inspection.
- 4.2 Ultrasonic thickness measurement.

5.0. Conditions Found

5.1. External

- 5.1.1 All painting and insulation found intact without any evidence of painting peel off or blistering and no evidence of any damage for insulation or insulation cover aluminum sheet.
- 5.1.3 All ladders, stairways and handrails found in satisfactory condition.
- 5.1.4 All concrete support found in satisfactory condition without evidence of cracking or spalling.
- 5.1.5 Manhole found in satisfactory condition without evidence of any corrosion.
- 5.1.6 All external piping insulation found in satisfactory condition.
- 5.1.7 All earthling lugs found in satisfactory condition.

5.2. Internal

- 5.2.1 All internals found in satisfactory condition without evidence of fallen down, damage or corrosion except some spray nozzle found lose and it fixed back properly.
- 5.2.2 All internal surfaces of shell and heads found in satisfactory condition, apart from normal carbon steel very thin hydroxide layer with some very shallow pitting.
- 5.2.3 All welds of shell and heads found in satisfactory condition without evidence of heavy corrosion.
- 5.2.4 All internal surfaces of connected nozzles and manway found in satisfactory condition without evidence of sever corrosion.
- 5.2.4 All thermos wells found in satisfactory condition.

5.8.1. Ultrasonic Testing

Ultrasonic thickness measurement was carried out on the internal shell courses and heads found satisfactory. Thickness measurement report available.

6.0. Recommendations

Review BFW deaerating process to assure absence of oxygen and mitigate oxygen further corrosion.


any

10. Inspection Grade and Interval

In accordance with the latest revision of SHAMS Code of Practice, this **Decerator was** endorsed for 48 months under class 2, for next Major Inspection.

Frequency : 48 Months. Endorsement : 48 Months Next Major Insp. due : March, 2024

Photos







International Inspection Services Ltd.

NON DESTRUCTIVE TESTING/HEAT TREATMENT/ADVANCED INSPECTION SERVICES, CALIBRATION SERVICES AND MECHANICAL & METALLURGICAL LAB SERVICES

intertek.com

Form No.: IN-QSF-36 Rev. 05E Dtd.: 20-10-2018

			RASONIC THI						
lient:	SHAMS POWER (COMPANY	THE REPORT OF THE PROPERTY OF	Martin Ramin Britannia Berlin (Berlin Berlin	AND THE PROPERTY OF THE PROPER				
ate:		03.03.2020		Report No.:		AD / 457			
roject:		SHAMS OUTAGE MARCH 2020		Job No. :		N/A			
cation:	n: MADINAT ZAYED		Drawing No.:		N/A CS				
m ID:	DEAERATOR - R1LLA10 BB001			Material:					
f/ Proc	Procedure No: INSPEC/UTG/001 Rev.10		Ref. Standard:		ASME SEC V				
UTG Equipment Model/ Manufacturer: USM 3		X DAC / GE	Serial No.:		7292a				
		STEP WEDGI	GE, IIW V2 BLOCK	EQPT Calibrat Date:	on Certificate	icate & Due INS/UT/CAL-04			
be Ty	pe/ uency:	WK TR 0° PROBE	/ 10mm DIA / 5 MHz		d Name & Typ	e:	POLYCELL + WATER		
nnecti	ng Cable Type &	LEMO TO MIC	RODOT & 2 MTR	Special Attach	100	STEP WEDGE BLOCK (SL NO			
ngth: st Tem	perature:	AN	1BIENT	Equipment/ B Surface Condi			AS CLEANED		
ar - marking and respective	n Date:		03.2020						
scription			73.2020	rage.	1 of		3		
						**72			
)R THI	CKNESS DETAILS R	REFER CONTINUATION SHE							
OR THI	LEXELUITE	- REPO	ORT FORMAT APPLIC	CABLE ONLY FOR AUH 8			Al / TPI		
OR THI	LEVEL II TE	CHNIGIAN SARI & SHYMAL PAUL	ORT FORMAT APPLIC		s FUJ FACILITY	Name:	Al / TPI		
	LEVEL II TE	- REPO	ORT FORMAT APPLIC		FUJ FACILITY		AI/TPI		
ne:	LEVEL II TEI	CHNIGIAN SARI & SHYMAL PAUL	ORT FORMAT APPLIC CLIE Name: Sign: Date:	ENT REPRESENTATIVE	FUJ FACILITY	Name:			
ne:	LEVEL II TELL AFZAL ANS Internet Suprement Sup	CHNIGIAN SARI 8-SHYMAL PAUL Sign 03-03-2020	ORT FORMAT APPLIC CLIE Name: Sign:		FUJ FACILITY C Email: inspec.d Email: inspec.d	Name:	COM POSICS PARTOS PRUNTIKOROUP		



International Inspection Services Ltd.
NON DESTRUCTIVE TESTING/HEAT TREATMENT/ADVANCED INSPECTION SERVICES, CALIBRATION SERVICES AND MECHANICAL & METALLURGICAL LAB SERVICES

intertek.com

Form No.: IN-QSF-36A Rev. 05E Dtd.: 20-10-2018

		(C	ONTINUATION SH	EET)				
ate:	03.03.2020	Report No.:	AD- 457		Page:	2	Of	3
LOCATION	ORIENTATION	ORIGINAL THICKNESS	MEASURED THICKNESS MINIMUM (mm)	DIMINUTION IN mm	DIMINUTION IN %		REMARK	
1	12"O"CLOCK	-	14.01	-	- Homester and the source scenarios source special contract of the special contract of the source special contract of the source special contract of the special contract	womeninentaninosis (DISH	MITTERNA
1	3"O"CLOCK	-	14.02	-	-		DISH	
1	6"O"CLOCK	-	14.03	-	-		DISH	
1	9"O"CLOCK	-	14.45	-	-		DISH	
2	12"O"CLOCK	-	15.60	-	-		SHELL	
· 2	3"O"CLOCK	-	15.30	-	-		SHELL	
2	6"O"CLOCK	-	15.60		-		SHELL	
2	9"O"CLOCK	-	15.60	-	-		SHELL	41-7000-000-000-00-0
3	12"O"CLOCK	-	15.70	-	-		SHELL	
3	3"O"CLOCK		15.20	-	.=		SHELL	
3	6"O"CLOCK	-	15.70	-	-		SHELL	
3	9"O"CLOCK	-	15.40	-	-		SHELL	******************
4	12"O"CLOCK	-	15.40	-	-		SHELL	
4	3"O"CLOCK	-	15.60	-	-		SHELL	
4	6"O"CLOCK	-	15.20	-			SHELL	
4	9"O"CLOCK	-	15.60	-			SHELL	
5	12"O"CLOCK	-	15.40	—	-		SHELL	
5	3"O"CLOCK	-	15.40		-		SHELL	
5	6"O"CLOCK	-	15.60	—	-		SHELL	
5	9"O"CLOCK	-	15.70	=	-		SHELL	
6	12"O"CLOCK	-	15.40	_	-		SHELL	
6	3"O"CLOCK	-	15.60	——————————————————————————————————————	-		SHELL	
6	6"O"CLOCK	-	15.70		-		SHELL	
6	9"O"CLOCK	-	15.40				SHELL	
7	12"O"CLOCK	-	15.70		_		SHELL	
7	3"O"CLOCK	-	15.60	——————————————————————————————————————	-		SHELL	
7	6"O"CLOCK	-	15.60	_	-		SHELL	
7	9"O"CLOCK	-	15.70		-		SHELL	
8	12"O"CLOCK	-	13.89		_		DISH	
8	3"O"CLOCK	-	13.90	-	-		DISH	
8	6"O"CLOCK	-	13.27	-	-		DISH	
8	9"O"CLOCK	-	14.02	-	-		DISH	
+	LEVEL II TECI	CONTRACTOR AND ADDRESS OF THE PROPERTY OF THE PARTY OF TH	APPLICABLE ONLY FOR	AUH & FUJ FACILITY T REP.		AI/TPI		
ne :	SHYMALI		Name :		Name :	AI/ IPI		
ı:	18 JE	\vee	Sign :		Sign:			
e : Branch	IPOBALONGULLINA. 05.03.20		Date : Fax: 04 3241957		Date :			
h Branch nabi Branch	PUBC 013 CAMON, U.A.E Date :-	Ter: 06 5361300	Fax: 06 5361173	Emall: inspec.dxbcoor@intertek.cor Email: inspec.shicoor@intertek.corr Email: inspec.adhcoor@intertek.cor			INSPECIS PART OF	INTERTE
n Branch Branch	: P O Box: 1937 Finairan, U.A.: : P O Box: 193, P.C: 131, Sultanate of Oman			Email: Inspec.fujcoor@intertek.com			For Complaints 8	0.0

intertek inspec

International Inspection Services Ltd


Intertek.com

Date :- 03.03.2020 Report No.:- AD-457

Page No. :- 2 OF 2

ULTRASONIC THICKNESS SCANNING DRAWING SHEET

DEAERATOR TANK



LEVEL II TECHNICIAN

★ UTG LOCATION

Name: SHYMAL PAUL & PEAL ANSARI
Sign: Sign A
Date : 56,03.2,020