SHAMS POWER COMPANY

ENGINEERING DIVISION

INSPECTION & CORROSION SECTION

SHAMS 1

LOCATION: R1QH10AC00 KKS: R1QH10AC00

GRADE & CLASSIFICATION: 2

CERTIFICATE OF INSPECTION

The equipment detailed below was examined in accordance with the SHAMS code of practice for plant inspection,

ITEM: Auxiliary boiler LOCATION: SHAMS Plant

TYPE OF INSPECTION: Major DATE OF INSPECTION: Jan, 2020

PLACE OF INSPECTION: IN-SITU DATE OF LAST INSPECTION: Jan, 2018

REPORT:

1.0. SUMMARY

The above boiler was taken off line, isolated, opened, vented & cleaned for major external & internal inspections.

2.0. SUBJECT

2.1. This fire tube boiler consisted of main water horizontal vessel, inside it a fire tube where burner mounted on it. Flaw gases goes inside one inch diameters tubes making two passes inside main water vessel before going to the atmosphere through vertical chimney

Size	
Design pressure	
Design temperature	
Operation pressure	
Operation temperature	
Fire tube material	
Shell material	

The above equipment is/ is not considered suitable for further service under the present operating conditions

NEXT MAJOR INSPECTION DUE: INSPECTED: Osman Ismail

ENDORSEMENT: 48 MONTHS

REVIEWED : Ali Al Masabai

3.0 HISTORY

This boiler was commissioned in 2013. It was experienced repeated leaks from welding tubes to tube sheet welding. It was re-wedded, tested and almost problem eliminated.

4.0. SCOPE OF INSPECTION

- 4.1. Visual Inspections were carried out on internal & external surfaces of the boiler following removal burner and internal cleaning. Internal surface condition of fire tube found satisfactory without any evidence of overheating, flame impingement, creep, or any dimension changes.
- 4.2. Visual Inspection of
- 4.3. Dye- penetrant test on tube sheet to tube welding.
- 4.4 Ultrasonic thickness survey on fire tube

5.0. CONDITIONS FOUND

5.1. External

- Insulation along with its cladding, connecting piping, safety valves, ladders, walkways, concrete foundation, burner, tube sheet covers, chimney all found in satisfactory condition.

5.2. Internal

- Internal surface condition of fire tube found satisfactory without any evidence of overheating, flame impingement, creep, or any dimension changes.
- welding of tube to tube sheet along with accessible parts of tube internal surfaces found in satisfactory condition.
- Some combustion products found deposited inside duct (outside boiler) under chimney.

5.3 NDT

- Thickness survey of fire tube carried found in satisfactory condition with average thickness 18.5 mm. Details in attached thickness survey report.
- Dye- penetrant test carried out on tube to tube sheet welds found satisfactory.

4.4. Insulation

Found in good condition along with cladding sheet

5.5. Supports

Found in good condition

6.0. Recommendations

Interval of safety valve testing and floating test after major maintenance and opening internals of valves should discussed and agreed.

7.0 Inspection Grade and Interval


In accordance with the latest revision of SHAMS Code of Practice, this boiler was endorsed for 48 months under class 2, for next Major Inspection.

FREQUENCY : 48 MONTHS. ENDORSEMENT : 48 MONTHS,

GRADE : 2

Next Major Insp. due : March, 2024

8.0 **Photos:**





Burner refractory and tube sheet cover



International Inspection Services Ltd.

NON DESTRUCTIVE TESTING/HEAT TREATMENT/ADVANCED INSPECTION SERVICES, CALIBRATION SERVICES AND MECHANICAL & METALLURGICAL LAB SERVICES

intertek.com

Form No.: IN-QSF-36 Rev. 05E Dtd.: 20-10-2018

			ULTRASONIC	THICKNESS GAUG	SING	REPORT			
Client:	SHAMS POWE	R COMPANY			E ETATALISTA PARTICIA	THE PARTY OF THE P			
Date:		05.03.	2020	Report No.		AD / 465			
Project:		SHAMS OUTAG	E MARCH 2020	Job No. :			N/A		
Location	ocation: MADINAT		AT ZAYED	Drawing N	0.:	N/A			
Item ID:			RY BOILER	Material:					
							CS		
	cedure No:		C/UTG/001 Rev.10	Ref. Standa	ard:		ASN	ΛΕ SEC V	
A TOTAL TOTAL STORY	G Equipment Model/ nufacturer:		SM 35 X DAC / GE	Serial No.:	Serial No.:		7	7292a	
Calibratio	on Block No. :	STEP V	WEDGE, IIW V2 BLOCK	EQPT Calib Date:	ration (Certificate &	Due	INS/UT/CAL-043/19/AUH	
Probe Ty		WK TR 0° P	ROBE/ 10mm DIA / 5			Jame & Tyne		POLYCELL + WATER	
Size/Frec Connecti	juency: ng Cable Type &	<u> </u>		Special Att	*** ** *** *** *** *** *** *** *** ***			FOLICELE + WATER	
ength:		LEMO T	O MICRODOT & 2 M	TR Equipment			STEP WED	GE BLOCK (SL NO : AZB270)	
Test Tem	perature:		AMBIENT	Surface Co	ndition:	:		AS CLEANED	
Inspectio	n Date:		05.03.2020	Page:	1	of		1	
Descripti	on:		The state of the s						
ULTRAS	SONIC THICKNE	SS GAUGING WAS CAI	RRIED OUT ON THE F	OLLOWING AUXILARY BO	ILER (R	1 QH 10AC0	01)		
OCATIO	<u>N</u> 01	RIENTATION	MEASURED THICK	(NESS (mm)					
1	1	2 O'CLOCK	18.40		THE PARTY OF THE P				
1	3	O'CLOCK	18.26						
1		O'CLOCK	18.33		-	MANAGE AND			
1		O'CLOCK	18.29					A STATE OF THE STA	
2	**************************************	2 O'CLOCK	18.27		NAMES OF THE OWNERS OF THE OWN				
2		O'CLOCK	18.34						
2		O'CLOCK	18.39						
3		2 O'CLOCK	18.30 18.38		····				
3		O'CLOCK	18.43		***************************************		***************************************		
3		O'CLOCK	18.59						
3		O'CLOCK	18.39		***************************************	The second secon			
4	1	2 O'CLOCK	18.58		***************************************				
4	3	O'CLOCK	18.46			market with the property of the second secon			
4	6	O'CLOCK	18.30		***************************************				
4	9	O'CLOCK	18.25			A CONTRACTOR OF THE PARTY OF TH	***************************************		
5	1	2 O'CLOCK	18.42						
5		O'CLOCK	18.43		THE STATE OF THE S				
5		O'CLOCK	18.46					MAYA Li a da d	
5	9	O'CLOCK	18.30			Co. 50000000 1100000 000000		and the second s	
			REPORT FORMAT	APPLICABLE ONLY FOR AU	H & FU	J FACILITY			
	LEVEL II	TECHNICIAN	133	CLIENT REPRESENTATIV	'E			AI / TPI	
lame :	(THE	SHYMALPAUL	Name :	The second secon		Na	me :		
ign :		Kight Families* Sign	Sign :			Sig	;n :		
ate:	Leve	60 05.03.2020	Date :				te:		
ıbai Branch	: C Box: 963	S. DUST, U.A.E.	Tel : 04 3241955	Fax: 04 3241957	Marine Committee Constitution of the Constitut	Email; inspec.dxbo	coor@intertek.com	INSPECTS PART OF INTERTEX GROUP	
iarjah Branch bu Dhabi Bran	ch : P O Box: 413	ō, Sharjah, U.A.E 27, Abu Dhabi, U.A.E 7. Fujairah, U.A.E	Tel: 06 5361300 Tel: 02 6225820 Tel: 09 2238754	Fax: 06 5361173 Fax: 02 6225830		Email: inspec.shjce Email: inspec.adho	oor@intertek.com coor@intertek.com		
ijairah Branch	: F. C. Best. 280			Fax: 09 2233754		Email: inspec.fujco			

★ UTG LOCATION Report No.:- AD-465 **Date:** 05.03.2020 Page No. :- 2 OF 2 ULTRASONIC THICKNESS SCANNING DRAWING SHEET International Inspection Services Ltd **AUXILARY BOILER** Intertek.com intertek inspec Name : Sexual PA LEVEL II TECHNICIAN Date :- 05.03.2020



International Inspection Services Ltd.

NON DESTRUCTIVE TESTING, HEAT TREATMENT, ADVANCED INSPECTION SERVICES, CALIBRATION SERVICES AND MECHANICAL & METALLURGICAL LAB SERVICES

intertek.com

Form No.: IN-OPF-04 Rev: 13E Dtd: 20-03-2019

Report No.:									
A THE CASE AS A SAME WAY A SAME	AD / 53664	4	Date:		05.03.2020	Page:	1 Of	1	
lient :	SHAMS POWER CO	OMPANY	Job No. :		PROJECT :- SHAMS O	UTAGE MARCI			
ocation :	MADINAT ZA	YED	Item :						
1aterial :	CS		Ref / Proc	edure No. :	INS/	ASME/PT/001			
nickness :	VARIOUS	Revision :	***************************************		22				
rface ndition :	AS WELDED & CL	.EANED	Test Temp	o. :	AMB	AMBIENT (25°)			
ondition : liewing DAY LIGHT (>1076 LUX) ondition :			Penetrant Type /		VISIBLE SOLVENT REMOVABLE				
enetrant	10 MIN	West of the second seco	Technique : Dev. Time:		(4) 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1				
vell time : ate of test :					10 MIN				
nsumables	05.03.2020	ACCP - Cri	teria :	ASME S	EC VIII DIV-1		The second second second		
pe & Batch	MAGNAFLUX - SPOTCHECK				*				
	Penetrant Remover		Penetrant			Develope	,		
SK	C-S (BATCH NO-180108) JAN 2021	- sk	L-SP2 (BATCH NO-171201) DEC 2020	SKD-S2 (B	ATCH NO-18 0 1	.02) JAN 2	021	
servation	& Evaluation :	A CONTRACTOR OF THE CONTRACTOR						· · · · · · · · · · · · · · · · · · ·	
					The state of the s				
.00% DPT W	AS CARRIED OUT ON THE FOLLOWING ITEM	1		W. W					
THE AMERICAN AND ADDRESS OF THE PARTY OF THE		*							
					•				
	FILER (R1Q1H-10AC001)			-					
	ILER (R1Q1H-10AC001) E ON TUBE END WELD JOINT								
				-					
T WAS DONI	E ON TUBE END WELD JOINT	TIME OF INSPEC	TION						
O RELEVANT	E ON TUBE END WELD JOINT	TIME OF INSPEC	CTION.						
PT WAS DONI	E ON TUBE END WELD JOINT	TIME OF INSPEC	CTION.						
PT WAS DONI	E ON TUBE END WELD JOINT	TIME OF INSPEC	CTION.						
PT WAS DONI	E ON TUBE END WELD JOINT	TIME OF INSPEC	CTION.						
PT WAS DONI	E ON TUBE END WELD JOINT	TIME OF INSPEC	CTION.						
PT WAS DONI	E ON TUBE END WELD JOINT	TIME OF INSPEC	CTION.		RESULT	ACCEP	-		
O RELEVANT	E ON TUBE END WELD JOINT		TAPPLICABLE ONLY FOR AUH &	FUJ FACILITY	RESULT	ACCEP!	-	ect	
PT WAS DONI	E ON TUBE END WELD JOINT INDICATION WAS OBSERVED DURING THE PTABLE AS PER THE SPECIFICATION.		ST APPLICABLE ONLY FOR AUH &	FUJ FACILITY	RESULT	2	-		
NO RELEVANT	E ON TUBE END WELD JOINT			FUJ FACILITY	RESULT Name:		-		
O RELEVANT OUND ACCES	E ON TUBE END WELD JOINT INDICATION WAS OBSERVED DURING THE PTABLE AS PER THE SPECIFICATION. LEVEL II TECHNICIAN AEZAL ANSARI & SHYMAL PAUL	REPORT FORMA Name: Sign:	ST APPLICABLE ONLY FOR AUH &	FUJ FACILITY		2	-		
PT WAS DONI	E ON TUBE END WELD JOINT FINDICATION WAS OBSERVED DURING THE PTABLE AS PER THE SPECIFICATION. LEVEL II TECHNICIAN AFZAL AND ARE SHYMAL PAUL OBJUST 2020	REPORT FORMA Name: Sign: Date:	ST APPLICABLE ONLY FOR AUH &		Name : Sign : Date :	AI / TPI			
PT WAS DONI	E ON TUBE END WELD JOINT INDICATION WAS OBSERVED DURING THE PTABLE AS PER THE SPECIFICATION. LEVEL II TECHNICIAN AEZAL ANSARI & SHYMAL PAUL OS 03 :2020 WE II NO Book Dollado Join Line 19 O Book Dollado Join Line 19 O Book 1227, About Joine 10 O Book 1227, About Joine	REPORT FORMA Name: Sign: Date:	NT APPLICABLE ONLY FOR AUH &	Email: Inspec.dx Email: Inspec.ah Email: Inspec.ah	Name : Sign :	AI / TPI	-		

inspec

International Inspection Services Ltd


Intertek.com

Date: 05.03.2020

Report No.:- AD-53664 Page No. :- 2 OF 2

LIQUID PENETRANT EXAMINATION - DRAWING SHEET

AUXILARY BOILER



★ PT DONE LOCATION

Name: AFZAL ANSARI & SHYMAL PAUL Sign i'v. Sign Ansari Date: 05:03:2020 LEVEL II TECHNICIAN