

Work order WO-20001

In progress · Repair · On site (field) · Opened Oct 3, 2026 · Due Oct 8, 2026

Customer

CUSTOMER

Katahdin Lumber

ACCOUNT

KAT-1004

PHONE

207-555-0130

MAIN CONTACT

Morgan Pelletier

ON SITEMike at the Millinocket yard,
207-555-0144

Unit

MAKE / MODEL

Hyundai 70D-9

SERIAL

HHKH FV30K00057

YEAR

2019

HOOR METER

9,120 h

FUEL

Diesel

CAPACITY

15,500 lb

OWNER

Katahdin Lumber

COMPLAINT

Mast chatters when lifting over 10 ft. Customer reports it started last week.

CAUSE

Worn mast rollers on the inner rail.

CORRECTION

Labor

DATE	TECHNICIAN	HOURS	WORK DONE
Oct 4, 2026	Sam Wrench	2.5	Diagnosed, measured roller wear
Oct 5, 2026	Sam Wrench	1	Travel

DATE	TECHNICIAN	HOURS	WORK DONE
------	------------	-------	-----------

Total labor: 3.5 h

Parts used

PART NUMBER	DESCRIPTION	QTY
-------------	-------------	-----

I confirm the work above was done.

Technician	Customer	Date
------------	----------	------