

Heads-up Notification

Form 1 / Stage 1 · Controlled EHS Form

Project: M3 South | Location: JE | System No: INC-2026-0065 | Must be completed within 2 hours of occurrence

1. PROJECT DETAILS & LOCATION

Project Name:	M3 South	Case Number:	INC-2026-0065
Incident Title:	Hand cut		
Date (YYYY-MM-DD):	2026-09-24	Time (24hr):	09:00
Location / Building:	JE	Floor / Level:	JE-Ground Floor
Specific Location / Grid:	S.502, S.502.1	Contractor(s) Involved:	Bilfinger
Further Investigation:	Required	Reported By:	Superadmin
Actual Severity Assessment:	Level 2 — Minor	Potential Severity Assessment:	Level 3 — Moderate

2. INCIDENT RECORDS & CLASSIFICATION

Select all that apply. Categorisation may change following the investigation.

☐ Near Miss	☒ No Treatment Injury	☒ First Aid Injury	☐ Medical Treatment Injury
☐ Restricted Work Injury	☐ Lost Time Injury	☐ Permanent Disability	☐ Fatality
☐ Occupational Illness	☐ Environmental Incident	☐ Property Damage	
Hazard / Observation Category: ☒ Cuts			

3. INCIDENT DESCRIPTION & CONSEQUENCES

Brief Description: What Happened?

TEST

What is the consequence of this incident?

TEST

IMMEDIATE ACTIONS TAKEN

Immediate Action Taken	Responsible Person / Team	Time Implemented
stop work and instruct all other workers	Jesper	09:30

NOTIFICATION SIGNATURES & SIGN-OFF

Submitted By:	Superadmin	Digital Signature:	 Signed by Superadmin
Reviewed & Approved By:	Superadmin	Approver Signature:	 Signed by Superadmin

Initial Incident Report

Form 2 / Stage 2 · Controlled EHS Form

Project: M3 South | Location: JE | System No: INC-2026-0065 | Must be completed within 24 hours of occurrence

PROJECT DETAILS & INCIDENT OVERVIEW

Project Name:	M3 South	Case Number:	INC-2026-0065
Incident Title:	Hand cut		
Date (YYYY-MM-DD):	2026-09-24	Time (24hr):	09:00
Location / Building:	JE	Floor / Level:	JE-Ground Floor
Contractor(s) Involved:	Bilfinger	Further Investigation:	Required

SECTION A. HEADS-UP SUMMARY

Type / Category:	First Aid Injury, Cuts, No Treatment Injury	Severity Assessment:	Level 2 — Minor
Location:	JE - JE-Ground Floor		
Initial Description:	TEST		

SECTION B. INCIDENT CATEGORY

Select all that apply. The categorisation may change following the incident investigation.

☐ Near Miss	☒ First Aid Injury	☐ Medical Treatment Injury	☐ Restricted Work Injury
☐ Lost Time Injury	☐ Property Damage	☐ Environmental Incident	☒ Personal Injury
Other Categories: ☒ Cuts			

SECTION C. INJURED / ILL PERSON DETAILS

Injured Person Name:	TEST	Company / Employer:	Bilfinger
Manager / Supervisor:	TEST	Job Title / Trade:	TEST
Length of Service in Project:	3	Experience in Role:	5
Worker Activity at Time:	TEST		

SECTION D. INCIDENT DESCRIPTION

TEST

SECTION E. PHOTOS FROM INCIDENT LOCATION

09
is of a change log is to show essential changes (history) made in a document, who made the change (date and revision).
a log helps the reader identify changes (history) made to of a document and may be applied to a subject for approval and re-approval.
a log may comprise the following information:
a of change
date of the employee making the change
revision number of the document after the change
a section or point of the document where the change was made
if description of the change
a log should be filled in the first time before the document is distributed for approval. In this case it will only contain the description "New document" for the first approved version. When the document is sent for re-approval, the change log should be filled in with all the changes made to the document.
a log may be applied by the means of electronic compare functions (e.g. MS Word Compare) or manually (e.g. by hand-drawn and instrumentation diagrams) or by a table (normally inserted as the last page).

Photo 1: Incident Location Evidence

Version	Section	
1.0	All	First Issue
2.0	All	Changes / Se
3.0	All	Total review i
4.0	All	Review and t

Photo 2: Incident Location Evidence



Photo 3: Incident Location Evidence




Photo 4: Incident Location Evidence

SECTION G. INJURY / ILLNESS INFORMATION

Nature of Injury:	TEST		
Treatment Provided:	No Treatment	Anticipated Absence:	0 days

SECTION H. TYPE OF ACCIDENT CATEGORIES

☐ Contact with an object or equipment	☐ Electrocution – electrical injury	☐ Malfunctioning/Defective tools and equipment
☐ Tool accidents	☐ Scaffolding accidents	☐ Asphyxiation – Confined space
☒ Cuts	☐ Accidents involving cranes and other equipment/Machinery	☐ Biological
☐ Slip, Trip and fall accidents	☐ Fire and explosions	☐ Psychological
☐ Falls from heights	☐ Exposure to hazardous materials and chemicals	☐ Extreme Temperature
☐ Falling objects from height	☐ Noise	☐ Radiation
☐ Push and pull	☐ Vibration	
☐ Transportation accidents	☐ Ergonomic	

SECTION I. INDICATE TYPE(S) OF INJURY

☐ Abrasion, Laceration	☐ Drowning or Suffocation	☐ Acute infection	☒ Wound
☐ Dislocation of body part	☐ Animal bite	☐ Electrical Injury	☐ Acute exposure
☐ Bruising or Contusion	☐ Concussion/Compression	☐ Psychological shock	☐ Poisoning
☐ Burn or Scald	☐ Amputation and Crush Injury	☐ Paralysis	☐ Hearing loss
☐ Fracture	☐ Frost bite	☐ Sprain	☐ Irradiation
☐ Other			

SECTION J. INDICATE PARTS OF THE BODY INJURED

Selected Injured Area(s):

● Wrist (R)

● Hand (R)

● Arm, Elbow (R)

FRONT VIEW

BACK VIEW

SECTION K. IMMEDIATE ACTIONS TAKEN

Immediate Action Taken	Responsible Person / Team	Time Implemented
stop work and instruct all other workers	Jesper	09:30

SECTION L. INITIAL ROOT CAUSE ASSESSMENT

Initial Root Cause:	TEST		
Environmental Conditions:	Normal	Equipment Involved:	Hand Tools

SECTION M. SUBMITTER & APPROVER SIGNATURES

Submitted By:	Superadmin	Digital Signature:	 Signed by Superadmin
Approved By:	Superadmin	Approver Signature:	 Signed by Superadmin

Form 2: Initial Incident Report — Revision & Return for Revision Audit Log				2 Events
Action / Status	By (Role)	Reason / Change Details	Date & Time	
Returned for Revision	Superadmin (sdfs)	add more information for body parts	24 Sept 2026 11:33	
Updated Initial Incident Report	Superadmin (Contractor / HSE Editor)	added location	24 Sept 2026 11:34	

Final Incident Investigation Report

Form 3 / Stage 3 · Controlled EHS Form

Project: M3 South | Location: JE | System No: INC-2026-0065 | Must be completed within 7 days of occurrence

PROJECT DETAILS & INCIDENT OVERVIEW

Project Name:	M3 South	Case Number:	INC-2026-0065
Incident Title:	Hand cut		
Date & Time:	2026-09-24 @ 09:00	Building / Location:	JE
Specific Location:	S.502, S.502.1	Contractor Involved:	Bilfinger
Category / Classification:	First Aid Injury, Cuts, No Treatment Injury		

INCIDENT DESCRIPTION

TEST

1. INVESTIGATION TEAM

#	Name	Position / Role	Company
1	TEST	Manager	NNE

2. INVESTIGATION DETAILS

Description of process, timelines, tools, parties involved, systems reviewed, equipment, and findings.

TEST

3. WITNESS STATEMENTS


Witness statements collected as part of the investigation. Signed forms attached in Mandatory Attachments.

Witness Name	Badge No.	Employer	Occupation	Statement / Description
TEST	3434	NNE	Manager	TEST

4. FISHBONE ANALYSIS – CAUSE AND EFFECT

Interactive Ishikawa diagram covering People, Machine, Method, Materials, Environment, and Measurement.

Fishbone Analysis – Cause and Effect



INCIDENT / EFFECT & PROBLEM STATEMENT

5. Incident / Effect Description	7. Problem Statement
TEST	test

6. 5-WHYS ROOT CAUSE ANALYSIS

Analysis of probable causes selected from the Fishbone Diagram.

Selected Cause for Analysis: TEST

Why 1test
Root CauseTEST

Selected Cause for Analysis: TEST3

Why 1test
Root CauseTEST

Selected Cause for Analysis: TEST

Why 1test
Root CauseTEST

IDENTIFIED ROOT CAUSES & CONTRIBUTING FACTORS	
8. Identified Root Causes	9. Contributing Factors
Root Cause 1: adfsadf Root Cause 2: adfas	• adfsfa • adfdsag

10. CORRECTIVE ACTIONS & PREVENTIVE ACTIONS (CAPA)			
Action Description	Responsible	Target Date	Status
TEST STATUS HISTORY: [COMPLETED] 24/09/2026, 11:44 by Superadmin — Status changed from PENDING to COMPLETED	TEST	2026-09-24	COMPLETED

11. SEVERITY ASSESSMENT	
SEVERITY BEFORE CORRECTIVE ACTIONS Level 2 — Moderate	SEVERITY AFTER CORRECTIVE ACTIONS Level 2 — Moderate
Severity Reduction Achieved: Level 2 (Moderate) → Level 2 (Moderate)	

12. LESSONS LEARNED
test

13. PHOTOS FROM INCIDENT LOCATION

09

Use of a change log is to show essential changes (history) made in a document, who made the change (date and revision).

• log helps the reader identify changes (history) made to a document and may be applied to a subject for approval and re-approval.

• log may comprise the following information:

- of change
- date of the employee making the change
- version number of the document after the change
- section or point of the document where the change was made
- description of the change

• log should be filled in the first time before the document is distributed for approval. In this case, only the description of the change should be filled in with all the changes made to the document.

• log may be applied by the means of electronic compare functions (e.g. MS Word 'Compare' or 'Compare & Merge') or by a table (normally inserted as the last page of the document).

Photo 1: Incident Location Evidence

Version	Section	
1.0	All	First Issue
2.0	All	Changes / Se
3.0	All	Total review i
4.0	All	Review and u

Photo 2: Incident Location Evidence

Photo 3: Incident Location Evidence

Photo 4: Incident Location Evidence

14. MANDATORY ATTACHMENTS CHECKLIST	
Checklist of mandatory project documents and evidence attached to this investigation.	
Mandatory Item	Attachment Status
Contractor's Incident Report	X Pending / N/A
Witness Statement Form	X Pending / N/A
Risk Assessment & Method Statement (RAMS)	✓ Attached
📎 Attached: Performance Review Pilot project - QEDZ - 2174.docx	
Training Records	X Pending / N/A
Permit to Work (PTW)	✓ Attached
📎 Attached: Svarbrev_til_Arbejdstilsynet_adgangsveje_2026.09.17.docx	
Safe Plan of Action (SPA)	X Pending / N/A
Evidence for Actions Taken	X Pending / N/A
Waste Disposal Invoice (if applicable)	X Pending / N/A

17. SIGNATURES & DISTRIBUTION SIGN-OFF

HSE Investigator Name:	Superadmin	Digital Signature:	 Signed by Superadmin
Reviewer Name:	Superadmin	Digital Signature:	 Signed by Superadmin

Document Attachment Appendix

Controlled EHS Attachment

Project: M3 South | Case: INC-2026-0065 | Document: Risk Assessment & Method Statement (RAMS)

APPENDIX: RISK ASSESSMENT & METHOD STATEMENT (RAMS)

Attached Document Verification & Vault Record

Attached File Name:	Performance Review Pilot project - QEDZ - 2174.docx
Document Category / Key:	Risk Assessment & Method Statement (RAMS)
File Format / Extension:	DOCX File (application/vnd.openxmlformats-officedocument.wordprocessingml.document)
Recorded File Size:	24 KB
Vault Reference Path:	/incidents/inc_1790242942055_5adf986900c2c80d.docx
Verification Status:	✓ Document Verified & Permanently Attached to Incident Record

Document Attachment Appendix

Controlled EHS Attachment

Project: M3 South | Case: INC-2026-0065 | Document: Permit to Work (PTW)

APPENDIX: PERMIT TO WORK (PTW)

Attached Document Verification & Vault Record

Attached File Name:	Svarbrev_til_Arbejdstilsynet_adgangsveje_2026.09.17.docx
Document Category / Key:	Permit to Work (PTW)
File Format / Extension:	DOCX File (application/vnd.openxmlformats-officedocument.wordprocessingml.document)
Recorded File Size:	81 KB
Vault Reference Path:	/incidents/inc_1790242956935_80e980d1e1430f29.docx
Verification Status:	✓ Document Verified & Permanently Attached to Incident Record

Weekly Safety Report WK 37



Leading Indicators

M3 North

- **Focus area(s)** – Awareness Campaign Winter preparation on PPVI
- **Focus area(s)** – Dust in work and Common area(s)
- **Focus area(s)** – spot check(s) High-risk work
- **Focus area(s)** – Orientation light in common areas
- **Focus area(s)** – demarcation – respecting contractors workareas

M3 South

- Focus on Site supervision and HSE/Contractors, list complete from NN ?
- Leading cause for late RAMS and PTW rejections.
- Construction and CQ collaborations going forward, manpower transfer started in JF
- Planning of drill, 24 Sept.

M3 Infrastructure

- High focus on welding & pipe cleaning procedures, House keeping , and waste management within welding areas as there is still need for minor improvement
- Maintain focus on M3 East due to increasing activities within that area, with **main focus** on Tent for storage, and walkways/access routes
- Supporting security topic regarding poor parking have been a topic last couple of weeks
- Creating compliance spot check among M3 Infrastructure contractors on high-risk activities – **Dialogue** based approach
- Documentation, implementation and follow-up from LTI has now been finalized and closed out
- **You are the expert** campaign/initiative have been taken up again due to new contractors and up manning among known contractors

Leading Indicators

C&Q JF

- **Focus area** – Check of PTW statuses for opening and closing on time
- **Focus area** – Hazardous media Process Acid-Base S&G protocol meetings
- **Focus area** – Working with 2 NN Permit Officers for familiarization for site, BEAMS and Permit Vision

C&Q JG

- **Focus area (s)** – New Ad-hoc rules for applying for Commissioning PtW in place.
- **Focus area (s)** – CSC trainings and Safety behaviour trainings are ongoing.
- **Focus area (s)** – Barriers still getting tampered or moved.
- **Focus area (s)** – ConM responsibility for Simops on C&Q tasks

Recent Incidents from week (37)

M3 North

- SI5677 (08.09.2026) – FAI – Electrical shock from lift

M3 South

- SI4804 (08.09.2026) – MTI – Minor cut to the hand
- SI4805 (08.09.2026) – FAI – Worker injured by wrench during pipe installation
- SI4810 (09.09.2026) – NM – Scaffold component dropped from the floor above
- SI4841 (09.09.2026) – NM – Struck by MEWP
- SI1104 (10.09.2026) – MTI – Electric shock

M3 Infrastructure

- **No** incidents within this period

Recent Incidents from week (37)

C&Q JF

- No incidents within this period

C&Q JG

- No incidents within this period

Authorities visit/actions week 37

M3 North

Date	Finding	Action	Comments
	No visits. Note: Last visit 17-08-2026		

Authorities visit/actions week 37

M3 South

Date	Finding	Action	Comments
07-09-2026	JF2-Painters and the importance of housekeeping, ergonomics when vaccum cleaning. Face mask to be worn when spraying water based product. Injunction given.-Bach Painters	JF2- Housekeeping,ergonomics.	Clean as you go.
	JG-Injunction for insufficient extraction whilst welding. Questions asked for Danish approved worker qualifications-MSL	Extraction while orbital welding as well. Improve on extraction points, positioning of suction dish.	Increased worker qualifications controls going forward, comment by DWEA.
	Aarsleff work zone, excavations, insufficient access routes. Work temporarily stopped by DWEA. Injunction given.	Improved supervision	Area set up within 15 mins after DWEA instructions. Totally unnecessary injunction.

Authorities visit/actions week 37

M3 Infrasctructure

Date	Finding – Observations	Action	Comments
	No visits. Note: Last visit 27-08-2026		








Drug and Alcohol Testing – week 37

Site	Finding	Action	Comments
M3 North	No test carried out in this period/week		
M3 South	No test carried out in this period/week		
M3 Infrastructure	One Alcohol test	Result 0%	Preventive personnel support

Monthly Data (Sep 2026)

	M3 North	M3 South	M3 Infrastructure
Total Manhours:	46.239	98.068	9.670
Total no. of people:	1723	3393	811
Days since last LTI:	94 Last LTI: 15.06.2026 (SI5053)	15 Last LTI: 02.09.2026 (SI4744)	34 Last LTI: 14.08.2026 (SI2280)
Incidents in this month:	Environment: 0 First Aid Incident: 1 Loss Time Injury: 0 Medical Treatment: 0 Near Miss: 0 Restricted work injury: 0 Total: 1	Environment: 0 First Aid Incident: 1 Loss Time Injury: 1 Medical Treatment: 2 Near Miss: 3 Restricted work injury: 0 Total: 7	Environment: 0 First Aid Incident: 0 Loss Time Injury: 0 Medical Treatment: 0 Near Miss: 0 Restricted work injury: 0 Total: 0
Safety focus for the month:	- Safety campaigns based on weekly trends - C&Q collaboration	CQ Collaborations Winter campaigns, check previous policy etc.	House keeping , including waste management and behavior initiatives

Roll-out – Last 13 months (15-Aug-2025 to 14-Sep-2026)

	M3 North	M3 South	M3 Infrastructure	Total
Total Manhours:	3.118.981	3.337.604	663.262	7.111.653
Total no. of people:	8003	10059	5314	15.141
TRIR (Total Recordable Incident Rate)	 Current TRIR (vs Last Month) ▼ -7.9%	 Current TRIR (vs Last Month) ▲ +1.5%	 Current TRIR (vs Last Month) ▼ -0.2%	 Current TRIR (vs Last Month) ▼ -3.3%
LTIR (Lost Time Incident Rate)	 Current LTIR (vs Last Month) ▲ +0.0%	 Current LTIR (vs Last Month) ▼ -4.5%	 Current LTIR (vs Last Month) ▼ -0.2%	 Current LTIR (vs Last Month) ▼ -2.0%

