SERVICE BULLETIN

GROUP: 00 - General Information	**DATE:** December 2006	**NO.** 00/2006/027_A
MODEL: All	**SUBJECT:** Introduction of the revised Service and Warranty Book. (Revision A)	
COUNTRIES: Australia	**D.R.BUDDEN** **NATIONAL SERVICE MANAGER**	
	Bulletin Consists of 1 Page	

This revision 00/2006/027_A replaces 00/2006/027.

Changes in this revision are highlighted in italics with the revision symbol. A

This Service Bulletin informs you of the introduction of a revised Service and Warranty Book Part No. **MR936026**. This book will be introduced as a running change, effective from November 2006.

Changes

1. Revised valve clearance check time allowance for DI-Diesel engines (common rail - ML Triton and NS Pajero).
2. Revised valve clearance adjustment schedule and time allowance for 4A9 engines (including Colt Cabriolet engine 135950).
3. Added valve clearance adjustment schedule and time allowance for 4B1, 6B3 and 6G7 MIVEC engines.
4. Delete valve clearance check requirement from 1500km service schedule.

Note:

- *The valve clearance check time allowance has been increased from 0.8 hours to 1.5 hours* ***for DI-Diesel engines (common rail -*** **ML Triton and NS Pajero).** A
  Please ensure that all staff involved in Service Administration are aware of the revised allowance.
- *The valve clearance check at 1500km service schedule has been deleted for all vehicles in line with MMC service requirements.*

Publication

Service and Warranty Book Part No. **MR936026** replaces MR935801.

NOTE: THIS BULLETIN SHOULD BE FORWARDED DIRECT TO THE SERVICE MANAGER FOR ACTION/DISTRIBUTION

Copyright © Mitsubishi Motors Australia Limited.
Reproduction in whole or part prohibited without written approval.