MITSUBISHI MOTORS AUSTRALIA LTD.
ABN 53 007 870 395

1284 South Road Clovelly Park
SA 5042, Australia
PO Box 8 Melrose Park
SA 5039, Australia

Customer Assistance Centre 1300 13 12 11

www.mitsubishi-motors.com.au

(SAFETY RELATED RECALL 010067 - FIRST NOTIFICATION NOVEMBER 2013)

Dear Mitsubishi Triton/Challenger Owner,

At Mitsubishi Motors Australia Ltd (MMAL), we are committed to continual product quality improvement to ensure the safety and satisfaction of all our customers.

We are writing to inform you that as a precautionary measure we are voluntarily recalling 11~12 M/Y Triton/Challenger model vehicles as it has been identified that there is a potential that these vehicles may be affected by the problem described below.

Description of Problem

There is a possibility of improper welding on Front Suspension Lower Control Arms (LCA) produced prior to Friday, 11 May 2012 which may result in the weld failing. If the weld fails, it will be readily detected by the driver as the vehicle will become unstable, pulling to either left or right side of the road. As a precaution prior to inspection, customers should operate the vehicle in a conservative manner to avoid excessive shock load on the parts that may be affected.

Customer Action Required

Our records indicate that you currently own one of the vehicles that have been identified as being affected and we ask that you contact your selling Dealer or, if that is not convenient, the nearest Mitsubishi Dealer to make an appointment to have the vehicles front suspension Lower Control Arms welds inspected and replaced if required.

To minimise any inconvenience to yourself please contact the dealer prior to presenting your vehicle.

If you do not have the Dealer phone number available, please call 1300 1312 11, select option 2 and enter the post code of your selling Dealer to be re-directed to that Dealer or your post code to be re-directed to the nearest Dealer.

If the vehicle shown on this letter is no longer registered in your name, please tick the appropriate box over leaf and fill in the details of the new owner (if known). Using the ***re-useable envelope*** provided, return this letter to the address shown on the Customer Feedback Form (no postage stamp required) so that we can update our records.

Your cooperation in taking this action will ensure that no further correspondence will be mailed to yourself on this subject.

When presenting your vehicle, please hand this letter to your Mitsubishi Dealer. This will be used by your Dealer to advise us that the correction has been carried out on your vehicle and enable our records to be updated accordingly.

If you require any further information relating to this recall please call 1300 13 12 11 and select option 4.

MMAL regrets any inconvenience caused to you by the need for this action which is taken in the interest of safety and continued customer satisfaction.

Please turn over

Yours faithfully
Mitsubishi Motors Australia Limited

D. R. Budden
Head of National Service

Customer Feedback Form

Please return to;
Supervisor – Service Division
Reply Paid 285
KENT TOWN DC SA 5071, Australia

Rego	
VIN	
Ext Reference no	Recall no
Customer ID	Recall status

Please place a cross [X] in the boxes below if applicable.

☐ The vehicle has been written off and completely destroyed

☐ The vehicle has been reported stolen and has not been recovered.

☐ I have sold this vehicle

☐ I have never owned this vehicle

To update address / contact details please print below.

Name

New Address

New Suburb State

New Post Code

New Registration No