MMAL DEALER BULLETIN

Bulletin Subject	**Kenwood SDA to Alpine**		
Applicable Model(s)	MR Tritons fitted with a Kenwood SDA unit		
Notice Category	**Service Campaign**	Technical Bulletin	**020220**
Service Group	54 Chassis Electrical	Latest Revision Issued	13/02/2026
Revision	B	MMAL Reference	N/A

⚠ Printed copies may not reflect the latest updates. Please consult the online version

Mitsubishi Motors Australia Limited (MMAL) is conducting a service campaign (effective from 15/10/2025) to replace the Kenwood SDA unit with an Alpine unit (conditions apply).

Dealer Responsibility

Dealers must check whether a vehicle has any outstanding campaigns by performing a Vehicle Search in the Warranty Portal and complete all outstanding campaigns as required. This must be done whenever an owner makes a service booking or presents a vehicle, or during new or used vehicle PDI.

Product Description

MR Tritons fitted with a Kenwood SDA unit (various part numbers).

Campaign No	Kenwood Part No	Alpine Part No	Alpine Part Description
020220	8740A039	EG100148	Display Multivision Kit (includes new user manual)
	28020W010P		
	28020W020P		
	28020W030P		
	28020W040P		
	28020W060P		
Retain the removed Kenwood unit for 90 days then destroy			

Pre-Conditions

Replacement of the Kenwood unit with an Alpine unit will be completed on vehicles that have experienced failure on multiple Kenwood units.
If the vehicle is experiencing a first-time failure of the Kenwood unit, the standard Kenwood exchange procedure is to be followed.

Process

B
A

- Confirm that at least one Kenwood exchange unit has previously been fitted in the vehicle. **Obtain Customer consent to replace Kenwood unit with Alpine unit.**
- Submit MiDealer Assist case with the required documents and trouble-shooting guide competed (refer to the Rectification Procedure below for details)
- MMAL will review each case and will determine if an Alpine unit is approved.
- Once approved, VIN will be loaded into this Service Campaign. Dealer will receive confirmation via MiDealer Assist case that part can be ordered.
- Install new Alpine unit, new microphone and fascia and test that all OK.
- Remove the old audio user manual (if in vehicle) and place new Alpine user manual in the glovebox.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Kenwood SDA to Alpine**		
Applicable Model(s)	MR Tritons fitted with a Kenwood SDA unit		
Notice Category	**Service Campaign**	Technical Bulletin	**020220**
Service Group	54 Chassis Electrical	Latest Revision Issued	13/02/2026
Revision	B	MMAL Reference	N/A

Parts Order Information

A

Part No.	Part name	Qty per Vehicle	Order Type
EG100148	Display Multivision Kit	1	**ZREC** (VIN based order)
Removed components are to be retained for 90 days then destroyed			

Rectification Procedure

Before commencing any work, the following steps **MUST** be followed:

1. Check the vehicle VIN matches the VIN printed on the repair order.
   STOP work if the VIN does not match and clarify the correct vehicle.
2. Confirm that the vehicle has had at least one audio unit replaced. If this is the first fault, then follow the standard Kenwood exchange procedure.
3. Photograph the VIN stamping for attachment to the repair order and claim.
4. Photograph the odometer reading for attachment to the repair order and claim.
5. Photograph the audio unit screen for attachment to the repair order and claim.
6. Take video evidence of the Customers concern (where possible) for attachment to the claim.
7. Complete the required trouble shooting guide (as per bulletin MMAL-25148) for attachment to the repair order and claim.
8. Log into MiDealer Assist and create a case using the following information:
   a. Title – "**MMAXXXXXXXXXXXXXX**" (ensure that the correct VIN is entered).
   b. Case Topic – select "**MiCare**".
   c. Case Subtopic – select "**MiCare – 020220 Kenwood SDA1 to Alpine**".
   d. The following documents **MUST** be attached to the case:
      i. Photo of the VIN.
      ii. Photo of the audio unit screen.
      iii. Copy of completed trouble shooting guide.
      iv. Evidence of the fault (video/s if possible).

A
9. Once the Alpine unit is approved:
   a. MMAL will load the VIN into 020220 service campaign.
   b. Dealer to order part.
10. Dealer to replace the Kenwood unit with the supplied Alpine unit and microphone, then test all is OK.
11. Remove and replace the audio unit user manual in the glove box.
12. Retain the removed Kenwood unit for 90 days then destroy.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Kenwood SDA to Alpine**		
Applicable Model(s)	MR Tritons fitted with a Kenwood SDA unit		
Notice Category	**Service Campaign**	Technical Bulletin	**020220**
Service Group	54 Chassis Electrical	Latest Revision Issued	13/02/2026
Revision	B	MMAL Reference	N/A

Campaign Claim Procedure

Submit a claim for this Service Campaign via the MMAL Warranty Portal.

Campaign	Claim Options	Labour Details	
		Operation	Time
020220	Replace Kenwood with Alpine	02022010	0.5H

A

Ensure that the MiDealer Assist case number is noted in the chat section of the claim.

Revision Details

Initial Release – 22/10/2025
Rev A – updated approval process – 09/12/2025
Rev B – Clarification on MiDealer Assist process – 13/02/2026

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.