HOTLINE FIX

Group: 11 Engine	**Original Date:** 5 December 2014	**No.** CJ11-003
Model: CJ Lancer	**Subject:** Oil cavitation type noise	
Revised on 04/02/2015..... (date) **Revised on** **01/03/2016**..... (date) **Revised on** ..... (date)	Michael Miller Manager, Field Service	
MMAL Ref P4332	**Document consists of 1 page**	

(1) **Subject**: Oil cavitation noise

(2) **Possible Cause**: MMC have investigated engines returned from the field that exhibited the oil cavitation type noise and have determined that the noise is generated by the oil relief valve. MMAL can advise that oil degradation can contribute to this concern.

(3) **Improvement**: MMC have advised that there will be no field fix or production fix for this issue. MMC has also advised that the noise has no influence to function and performance of the engine.

(4) **Field Fix/Action**: On a customer complaint basis, explain that this is normal operating noise and that there is no long term effect on function or performance of the engine. If the customer insists that some action be taken, advise them that an engine oil change will address the concern however this will be at customer cost. When speaking with the customer, please obtain the following information that is dot pointed below and can also been found in the owners hand book.

Vehicles operating in certain conditions (shown below) can suffer from premature engine oil degradation and require more frequent attention (for example oil change)

- Frequent short running
- More than 50% of driving in city heavy traffic
- Prolonged idling or stop start driving
- Sustained high speed driving
- Continuous operation at higher than normal loading (operation at high RPM, towing, etc.)

(5) **Parts and Warranty Information:** No warranty is applicable for this concern as MMC have advised that there is no influence to function and performance of the engine. Please refer to the service and warranty booklet for additional servicing requirements.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.