HOTLINE FIX

Group: 54 - Electrical	**Original Date:** 11th May 2015	**No.** CJ54-008, XA54-005, ZJ54-002
Model: CJ Lancer, XA ASX, ZJ Outlander	**Subject:** Mitsubishi Link system Hands Free Module cannot be unlocked	
Revised on ..... (date) **Revised on** ..... (date) **Revised on** ..... (date)	Yoshi Tatewaki Manager, Field Service.	
MMAL Ref Information only	**Document consists of 1 page**	

(1) **Subject**: Mitsubishi Link system Hands Free Module cannot be unlocked

(2) **Applicable Models**: 13MY vehicles fitted with the display audio unit (not MMCS).

(3) **Possible Cause**: The 13MY Display Audio unit (P/No 8701A490) software does not incorporate the unlock function for the Hands Free Module in the "Diagnosis mode" section. This function is required only if the customer locks the Bluetooth module and cannot remember the code entered to unlock the module.

(4) **Improvement**: The 14MY Display Audio unit (P/No 8701A560) software has been updated to allow unlocking of the Hands Free Module via "Diagnosis Mode".

(5) **Field Fix/Action**: If a customer presents with a locked Hands Free Module on a vehicle fitted with a 13MY display audio unit and the code cannot be remembered, the hands free module will need to be replaced. As this feature is initiated by the customer, it is not considered a manufacturing concern and is not covered by warranty.

Alternatively, the module may be unlocked, at the customer's expense, via one of the following methods (Where access to an appropriate vehicle is available):

- Temporarily fit a 14MYDisplay Audio unit from a donor vehicle and perform the "Erase the Password" procedure from the workshop manual.

- OR -

- Temporarily fit the locked Hands Free Module to a vehicle fitted with 14MY Display Audio or 13MY onward MMCS unit (MELCO) and perform the "Erase the Password" procedure from the workshop manual.

(6) **Parts and Warranty Information:** Information only, warranty is not applicable to this concern.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.*

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.