MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395
Head Office
1284 South Road Clovelly Park, S.A. 5042
PO Box 8, Melrose Park South Australia 5039
Ph: +61 1300 13 12 11 Fax: +61 1300 55 33 19

3 June 2016

General Letter GL-16-016 Rev.B

To: ***Service Managers (cc Dealer Principals).***

Subject ***Triton & Challenger 4D56 Engine Overheat SCA Requirement***

This GL has been revised due to MMC requirements.

This General Letter is being revised to notify Dealers of the reporting requirements for ALL 4D56 Engine Overheat related warranty claim repairs (including engine overheat post campaign)

Requirements:

- **Copy of Front & Back of R/O including DTC**
- **Copy of Original R/O and Campaign Worksheet**
  1) If you have completed the Original Campaign, and
  2) If Engine Overheat occurred Less Than 30 Days or 3,000km, whichever comes first, from the Original Campaign date
- **Authority Code (PWA)**
  If a PWA was issued – list it the SCA comments during submission
- **Additional Diagnostic Time Allowance**
  1.50 Hours Maximum when Long Engine Used
  1.00 Hours Maximum when Short Engine Used
- **DQR or DQR Number**
  Listed in the SCA comments if already submitted
- **Photos – Clear "Cylinder Block Surface" and "Engine Number"**
  Photos of the defect Areas inserted into the Spreadsheet Photo Tab including VIN (Refer MN14-001)
- **MN14-001 Excel Spreadsheet**
- **Position Code (Failure)**
  111110 - Cylinder Block on the Claim and SCA
- **Labour Operation Code**
  110012 10 for Long Engine (Refer to the Operation Code Manual on the Dealer Portal)
  110011 10 for Short Engine (Refer to the Operation Code Manual on the Dealer Portal)
  Additional operations can be selected when applicable.
- **Misc. Parts Value**
  Oil, coolant and sealant usage costs must not exceed the quantities added by the technician or the total system capacity unless justified by technician explanation. These quantity's must be listed on the R/O
  Note: Refer to GL-14-028 for the current Fluid and Lubricant value.
  Refer to Total dry fil capacity, including heater core if drained.

Others:

- Technician's clocking times to be supplied and campaign check sheet as described in step 5B in MN14-001 if applicable.
- Additional information may be requested on a case by case basis.

Copyright © Mitsubishi Motors Australia Limited
Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. 2: This General Letter forms part of the Service Procedure Manual

Reference to warranty claiming codes and authorisation requirements have been removed

Yours sincerely,
Mitsubishi Motors Australia Limited



Yoshi Tatewaki
Head of Field Service & Warranty
.

Copyright © Mitsubishi Motors Australia Limited
Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. 2: This General Letter forms part of the Service Procedure Manual