MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395
Head Office
1284 South Road Clovelly Park, S.A. 5042
PO Box 8, Melrose Park South Australia 5039
Ph: +61 1300 13 12 11 Fax: +61 1300 55 33 19

22 July 2016

General Letter GL-16-031


To: ***Service Managers (cc Dealer Principals)***

Subject ***Service and Warranty booklet Perforation Corrosion Warranty statement***

The purpose of this General Letter is to advise of the omission of the Perforation Corrosion Warranty statement in the new Generic Service & Warranty booklet.

MMAL are producing a sticker with the **Perforation Corrosion Warranty** statement that will need to be placed inside the back cover of the booklet as indicated below in the diagram.

These will stickers will be distributed shortly and need to be used in the short term until new booklets are available. In the event of a vehicle being sold to a customer before the stickers arrive and the vehicle has the new type of booklet, please make sure the Perforation Corrosion Warranty statement is added to the book before being distributed using the statement contained within the attachment to this General Letter.



Thank you for your understanding on this matter.

Yours sincerely,
Mitsubishi Motors Australia Limited

Yoshi Tatewaki
Head of Field Service & Warranty

Copyright © Mitsubishi Motors Australia Limited
Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. 2: This General Letter forms part of the Service Procedure Manual