MMAL DEALER BULLETIN

BULLETIN: MMAL-23044

DATE: 14 October 2024
DATE: 13 January 2026 (Rev C)

ATTENTION: Service Managers (cc Warranty Clerks and Fixed Op Managers)

Audio Unit Exchange Process

Dear Valued Business Partners,

MMAL is experiencing increased demand for multiple different exchange units for the following vehicles (and audio unit part numbers):

Mi-Display

Triton	AU600034 AU600035

SDA1 (Kenwood)

Various	28020W020P 28020W060P 8740A039

SDA2 (MELCO)

Pajero Sport	8740A045 8740A046 8740A192
ASX	8740A075 8740A112 8740A138
Outlander	8740A100 8740A123 8740A104

MMAL has increased the number of core stock units for particular models within the exchange program. However due to the consistent demand for these units, the return of all units in a timely manner is still required.

Note:
An RCTI for Dealer netting will be issued for the replacement cost of exchange units not returned within 60 days of dispatch. If the Dealer has a concern with invoicing raised, please contact MMAL via MiDealer Assist.

For simplicity we have added all exchange program processes into this single document. Please see the below steps for each exchange program:


Mi-Display

SDA1 – Kenwood

SDA2 – MELCO

Warranty Procedure

Yours sincerely
Mitsubishi Motors Australia Limited



JEFF MARTIN
GENERAL MANAGER – CUSTOMER, TECHNICAL AND WARRANTY

MI-DISPLAY

If a fault is found with a Mi-Display unit, follow the below exchange program process.

Note: The Mi-Display Warranty is partly covered by the supplier, DIRECTED Electronics Australia Ltd. Please refer to their Warranty Statement below:


"This accessory is a Supplier Branded Accessory and is not manufactured or warranted by Mitsubishi Motors. The manufacturer of the accessory provides the warranty. The information provided relating to the accessory is based on information provided by the accessory manufacturer."

All warranty "equipment" claims are to go direct through DIRECTED Electronics, please follow DIRECTED electronics warranty procedure as follows:

- Creation of claims to DIRECTED Electronics Australia are initiated through their "FRESHDESK" portal.
- This service is accessed by following the link provided below. Creation, management & tracking of claims are all managed through "FRESHDESK".
- As part of the launch of this service, DIRECTED Electronics has provided a user guide to help each dealership through the process (refer attachment – "How to raise a ticket").
- It is recommended that Dealers only create a single "FRESHDESK" account per Dealership Service Department, should multiple accounts be created visibility on tickets will be lost.
- Once a ticket has been raised, DIRECTED will initiate shipping (where required) of a replacement unit to the dealership. This is to ensure we get Customers back on the road as quickly as possible. The return process for any faulty Mi-DISPLAY unit back to DIRECTED is detailed within this warranty flow (refer warranty claim flow).

Process:

- Customer presents with a concern
- Dealer refers the Trouble Shooting Guide (TSG) carefully on the DIRECTED portal first before raising a ticket. The TSG can be found - https://midisplay.directed.support/support/login
  NOTE: For Carplay USB connection concerns, please ensure customer is using a GENUINE Apply USB cable before raising ticket.
- Dealer raises a Mitsubishi – Directed support ticket (through the Directed portal –can be found in appendix 1)
- If replacement unit required, Directed will dispatch replacement unit along with a pre-paid return satchel (for the old unit to be promptly returned)
- Dealer to return faulty unit to Directed via the return pre-paid satchel.
- Customers who have experienced failures on more than one unit may be eligible for a replacement Alpine unit – refer Service Campaign 020225.




The information contained in this document is confidential and intended for Mitsubishi Dealer internal use only.

SDA1 – KENWOOD

Once your Dealer order is entered into the exchange program (Process can be found in appendix 2), Kenwood will dispatch exchange units via StarTrack services as soon as practical.

Process:

- Contact Customer and fit exchange SDA unit within 10 business days of receipt of exchange unit.
- Each exchange order has a matching connote created for you to use for returning the original unit. It is essential the matching connote is used for the correct returning unit to allow tracking and credit for the Dealer.
- Do not include more than one return unit under the same connote.
- Dispatch original SDA with its matching connote on the same day it is removed (or ASAP) to ensure exchange stocks continue to be available for assessment, repair and re-issue.
- If you have lost a return connote, please contact Kenwood for a replacement.
- Keep a copy of the return connote for proof of return.
- C Customers who have experienced failures on more than one unit on MR Tritons ONLY may be eligible for a replacement Alpine unit – refer Service Campaign 020220



QUICK REFERENCE GUIDE

SDA2 – MELCO

If a unit has been supplied via the exchange program please follow the below steps:


Once your Dealer order is entered into the exchange program (Process can be found in appendix 2), MELCO Australia will dispatch exchange units via StarTrack services as soon as practical.

Process:

- Contact Customer and fit exchange SDA unit within 10 business days of receipt of exchange unit.
    - If it is not possible to fit the exchange unit to the Customer's vehicle, re-allocate the exchange unit to a different available Customer by completing the RE-ALLOCATION REQUEST_AUDIO form and emailing the form back to MELCO. (Bulletin MMAL-22214)
- Each exchange order has a matching connote created for you to use for returning the original unit. It is essential the matching connote is used for the correct returning unit to allow tracking and credit for the Dealer.
- Do not include more than one return unit under the same connote.
- Dispatch original SDA with its matching connote on the same day it is removed (or ASAP) to ensure exchange stocks continue to be available for assessment, repair and re-issue.
- If you have lost a return connote, please contact MELCO for a replacement.
- Keep a copy of the return connote for proof of return.

Alternatively, if a unit has been supplied via the service campaign follow the procedure manual from Active – Dealer Portal User Guide – Melco Returns.

This procedure can be found: SAP > My Work > Service > Latest Service Campaign



APPENDIX 1 – DIRECTED PORTAL

This portal is used to raise a support ticket in relation to Directed's audio head unit & associated products, for both Warranty or Non-Warranty requests.


It is good practice to set up one generic account per dealership for the Directed portal so multiple people can review and update tickets (contact Directed for assistance if needed).

Directed are available to help Dealers who need further assistance via a dedicated technical help line on 03 8331 4800 (Option 3,3). Please take advantage of this service whilst the vehicle is still at your dealership.


Access via the following link

https://midisplay.directed.support/support/login

Initial Login & Account Setup



This is the initial Login / Sign up screen. Once registered, please sign in to raise support tickets, view progress of tickets, responding to tickets and access to the "Knowledge base".




First time users to select "**SIGN UP**", then enter your full name, email address and then select "**REGISTER**".

You will receive an activation link via your email address. Click on the link and follow the instructions, such as creating a password. Once activated you will have access to the portal. Please check Junk / Spam emails also if you haven't received the activation email in your normal inbox.

The information contained in this document is confidential and intended for Mitsubishi Dealer internal use only.

QUICK REFERENCE GUIDE

Logged in Home Screen




After login, you will be taken to this screen. This is where you can raise a "**New Support Ticket**", "**Check Ticket Status**" and access the "**Knowledge base**".

"**Knowledge base**"


This is where you will be able to find Help Articles, Troubleshooting Guides, Installation Instructions, User Manuals, etc.

This will be updated from time to time, so always check here for

Raising a New Support Ticket




QUICK REFERENCE GUIDE




APPENDIX 2 – EXCHANGE PROCESS (KENWOOD/MELCO)

1) Log an exchange request through the SAP portal
   SAP > My Work > Service > Service Operations (MMAL) > Component Exchange> New Request




2) Enter in all details (note your Dealer details will automatically populate)



3) Click Next

4) In the Mitsubishi Part No field click on the Possible Entries button  to display the drop down menu, then select the required part number.

Note: Do not use the part number as the serial number when submitting a new request, if the part number is used in both fields the system will flag as a duplicate and will not be processed.



5) Click the Submit Request button to proceed with the request.
   a. Clicking on Save Request to save the request so that you can submit it at a later date.
   b. Clicking on Preview will display the form generated by the request.
   c. Clicking on Exit will allow you to exit from the request without saving. A warning message will display confirming you wish to continue.
   d. Clicking on Back will allow you to navigate to the previous page without losing the data entered.
6) Click save and submit

WARRANTY CLAIM PROCEDURE

1) If an exchange audio unit is required, then the audio unit may need to be removed to locate the serial number on the audio unit. After recording the serial number, refit the audio unit and order the replacement exchange audio unit.

2) A warranty claim may be submitted for obtaining the failed audio unit serial number. The cause part for this process is XAUDIO1 and the work code is 00 on the labour operation code.

3) When the exchange unit is replaced a second warranty claim may be submitted for the replacement of the exchange audio unit. The cause part for this process is XAUDIO2 and the work code is 10 on the labour operation code.

4) The value of XAUDIO, XAUDIO1 and XAUDIO2 is zero dollars ($0.00), and the repair dates will be the date the repair was completed or the date the serial number was recorded if using the XAUDIO1 scenario.*

	Claim 1		**Claim 2**	
Unit	**Cause Part**	**Work Code**	**Cause Part**	**Work Code**
Serial No. obtained **without** removal of unit	XAUDIO	10		
Serial No. obtained **by** removing unit	XAUDIO1	00	XAUDIO2	10

The information contained in this document is confidential and intended for Mitsubishi Dealer internal use only.

MODEL NUMBER LOCATION

SDA2



SDA1




Mi-Display



SDA2 CONNOTE – VEHICLE REFERENCE LOCATION

MELCO will reference the Dealer's RO on both documents (as highlighted below in yellow).



MITSUBISHI ELECTRIC
Changes for the Better

MITSUBISHI ELECTRIC AUSTRALIA PTY LTD

ADVANCE REPLACEMENT
314379040

Ship-to Address
[redacted]

Bill-to Address
[redacted]

Document Date	06/09/2023
Currency	AUD
Customer Account No.	100866
Customer PO No.	718696
Payment Terms	30 Days Net
Service Notification	80513187
Sales Order No.	6499032
Delivery No.	79438177
Page	1 of 1

Item	Material	Description	Quantity	Unit Price	Total Amount
010200	8740A100	AUDIO EXCHANGE (NR-201EM0LND0-T) 3AP611	1		

UNIT HAS BEEN EXCHANGED NEW S/N: 0926P049

PLEASE RETURN FAULTY UNIT 02137432

ON CON NOTE SUPPLIED: 66FZ50005311

To book a pickup for this return please call StarTrack 13 23 45 - MEAust Account 10150723

PLEASE RETURN FAULTY UNIT TO MEA WITH COPY OF THIS INVOICE, SIGNED.

****VERY IMPORTANT NOTICE:****
FAILURE TO RETURN THE FAULTY UNIT WITHIN 14 DAYS AN INVOICE WILL BE ISSUED FOR THE UNIT.

NOTE: ANY DELAY PLEASE ADVISE US ON 1300 651 808.



EXP *RETURN*
STARTRACK CONNOTE: 66FZ50005311
MITSUBISHI ELECTRIC AUSTRALIA - SERVICE
348 VICTORIA ROAD
RYDALMERE NSW 2116

651808 RYDALMERE 2116
AU SYD

EXP2116SYD

FROM: [redacted] PH: 0288787811

AR 80513187/6499032
RO 718696
RA NUMBER: 0

DATE: 05/09/2023 UNIT: CTN ITEM 1 OF _ WEIGHT: 3kg CUBE: 0.027

Article ID:66FZ50005311EXP00001