MMAL DEALER BULLETIN

BULLETIN: **MMAL- 25209** **DATE:** **22/12/2025**

ATTENTION: **All Dealer Principals**

New Mandatory Tool Distribution – Core Plug Removal and Installation Tool for 4N15 Engine

Dear Valued Business Partners,

Coolant seepage/leakage from the rear core plug affecting certain Triton and Pajero Sport models has been reported through the Dealer Network in increasing numbers. MMAL is aware that repairs associated with this concern have at times required extended repair and Vehicle Off Road times. Consequently, customers have experienced long wait periods, impacting both customer satisfaction and workshop productivity.

In response, the MMAL Technical Team has developed and validated a new Special Service Tool that enables in-situ replacement of the Core Plug to expedite these repairs. Please note that this new repair method is only approved for vehicles outside of the warranty coverage period of 3 years/100,00km from RDA (whichever occurs first). The revised Hotline Fix MQ/MR/QE/QF14-001, will be issued to detail the correct use of this tool.

Bosch will commence distribution of the tool (Part Number: EG100141) to all service centres from 19 December 2025. Your dealership should receive the tool within the following week. If the tool has not been received within two weeks from the commencement of distribution, please contact MMAL via Mi-Dealer Assist.

The cost of the tool is $333.34 (excluding GST and Freight). Each dealer will be charged through the P&A process in January 2026.

Thank you for your continued support.

FIONA LAMOND

Warranty Administration Manager

JEFF MARTIN

General Manager: National Field Support

MITSUBISHI MOTORS AUSTRALIA LIMITED ABN 53 007 870 395
The information contained in this document is confidential and intended for Mitsubishi Dealer internal use only.
Commercial In Confidence