HOTLINE FIX

Group: 13 - Fuel	**Original Date: 27th October**	**No. MN13-014**
Model: MN Triton	**Subject: Surge/Buck at 80-110km/h with cruise control set (4D56 MT)**	
Revised on ..... (date) **Revised on** ..... (date) **Revised on** ..... (date)	Y Oda, Deputy Director, Aftersales	
MMAL Ref P4765	This document consists of 1 page.	

(1) **Subject:** Surge/Buck at 80-110km/h with cruise control set (4D56 MT)

(2) **Possible Cause:** Due to varying component tolerances in the manufacturing process, fluctuations may occur in the vehicle speed signal sent to the engine ECU under some circumstances. As such, the target cruise control torque value calculated by the Engine ECU may be judged incorrectly, when target vehicle speed (cruise set speed) and actual vehicle speed are compared. This can lead to variations in delivered engine torque, causing a surging/bucking sensation in the vehicle.

(3) **Production Fix**: N/A (vehicle no longer in production).

(4) **Field Fix/Action:** On a customer complaint basis only, update the Engine ECU software as per the below applicability chart –

Model	Data Number (MFF)	ECU P/N	Software Part Number	
			Current	New
10MY 4D56 MT H/P	1862C722	1860B347	1860B347 01 – 1860B347 04	1860B347 05
11-13MY 4D56 MT H/P	1862C723	1860B583	1860B583 01 – 1860B583 06	1860B583 07
14-15MY 4D56 MT H/P	1862C724	1860C267	1860C267 01 – 1860C267 02	1860C267 03

(5) **Warranty Information:** Standard terms and conditions apply.

Hotline Fix MN13-014	**Surge/Buck at 80-110km/h with cruise control set (4D56 MT)**		
Claim header tab	Claim Type	YC01	
	Item 1	Item Type	Miscellaneous Parts
		Part No.	Reflash
		Dealer Quantity	1
		Part Causing Damage	☑
		Claimed Amount	$0.00
		Position Code	178501
		Complaint	99
		Circumstance	As per customer complaint
		Diagnosis Code	8A
		Notes	Hotline Fix MN13-014
	Item 2	Labour Operation	178501 TB
		Dealer Quantity	1
		Item Type	Labour Value
Labour Allowance	As per LOTS time		

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.