Mitsubishi Motors
Australia Limited
ABN 53 007 870 395

1284 South Road
Clovelly Park SA 5042
PO Box 8
Melrose Park SA 5039
Australia

Customer Assistance Centre
1300 13 12 11
Telephone +61 8 8275 7111
Facsimile +61 8 8275 6841

January 2002

Warranty Information Bulletin WIB 2002-01

Re: Lancer & L400 Dealer Fit Air Conditioning

ATT: SERVICE MANAGER/ WARRANTY CLERK

To contact Warranty Payments:

Telephone Warranty Hot Line: (08) 8275 6709

Fax: (08) 8275 7745

eMail: mmal_warranty_admin@mmal.com.au

Lancer & L400 Dealer Fit Air Conditioning
There still appears to be a lot of confusion over how to claim for dealer fitted air conditioning. Below is a summary of the current situation.

Pet Name	Model Code	Value
Lancer	CE0M21 CE0M41	$170.00
StarWagon GL	WA6M35 WA9M35	$250.00
StarWagon GLX	WA4H35	$450.00

Note: These Values include Vehicle Preparation and therefore this is not to be claimed separately.

Claim Details

Vehicle Information	As per normal Warranty Claim
Transient Owner	Not Applicable
Claim Type	W

Quality Information	
Complaint	Not Applicable
Circumstances	Not Applicable
Position Code	060010
Diagnosis Code	DF

Labour Information	
Position Code	060010

Mitsubishi Motors
Australia Limited
ABN 53 007 870 395

1284 South Road
Clovelly Park SA 5042
PO Box 8
Melrose Park SA 5039
Australia

Customer Assistance Centre
1300 13 12 11
Telephone +61 8 8275 7111
Facsimile +61 8 8275 6841

January 2002

Work Code	DF
Claimed Value	See Table Above

Part Information	
Causal Part	A/CKIT (Please note NO SPACES)
Claimed Value	$0.00

Remarks	**"A/C Serial Number: xxxxx" (where xxxxx represents the serial number of the A/C unit supplied)**

NIMBUS SCHEDULED SERVICE TIMES

Scheduled Service (Km)	Position Code	Work Code	Allocated Times (Hrs)
15,000	050015	SS	1.0
30,000	050030	SS	0.7
45,000	050045	SS	0.8
60,000	050060	SS	0.7
75,000	050075	SS	1.0
90,000	050090	SS	1.5
105,000	050105	SS	1.7

NOTE:

1.The use of "SS" as the work code.

2."SS" should also be used as the Diagnosis Code on all Scheduled Service claims.

PARTS DISPOSITION FOR RECALL PROGRAM 010008 AND SERVICE PROGRAM 020017

The above mentioned programs for NM Pajero called for parts to be destroyed while subsequent Disposition Lists asked for parts to be stored for 90 days. The Disposition Lists were in error. Any dealer who has stored these parts can destroy them in accordance with the related program.

Richard Wyatt

Manager Warranty and Technical Publications

Issued by MMAL Warranty Administration 9/01/2002