MITSUBISHI MOTORS
Spirited Cars for Spirited People
1300 13 12 11 | www.mitsubishi-motors.com.au

WARRANTY INFORMATION BULLETIN

WIB 2003-05 23/10/2003

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Warranty Hotline / Email Response Time

Due to a temporary reduction in available staff in the warranty department the response time for warranty queries is longer than we aim for. In some cases responses have been up to 3 days instead of the usual 24 hours. This situation should improve over the next fortnight when staffing levels increase. We would expect that there would be a gradual improvement over this period as we catch up on the backlog. Your patience in this matter is appreciated.

The Warranty Top 10

The following is a summary of the Warranty Top 10.

1. Position/Quality Codes not matching Causal Part.
2. Incorrect use of miscellaneous part numbers such as XAUDIO, XCLUSTER, A/CKIT, FOCxxxxx, etc. A computer will not recognise A/C KIT as the same as A/CKIT. The space makes a difference. The use of FOCxxxxx (where xxxxx could represent various parts) will usually be used on Recalls/Service Campaigns and Hotline Fix's. In this case follow the instructions given EXACTLY.
3. Recalls and Service Campaigns are usually released with details on how to complete the warranty claim. Failure to follow these instructions will result in the claim being rejected. Particular attention should be paid to campaigns with multiple operation options.
4. Recalls are judged by matching 3 critical elements, the recall number, the VIN, and the reference number. If these 3 elements on the claim do not match the information on DEACON the claim will be rejected.
5. Arrival Damage claims are NOT processed by the warranty department. These claims are processed in batches and could be held up while the transport department wait on other information necessary to process the claims. Constant phone calls to the warranty department will not speed this process up.
6. Battery claims are processed in accordance to General Letter – GL-02-029. Failure to follow these instructions will see claims rejected. In particular the inclusion of the 8 digit code in the remarks is imperative.
7. Diagnosis time on a claim MUST be authorised.
8. Disposition lists should only be faxed OR sent by post NOT both.
9. When leaving messages on the voice mail system please leave a contact name AND your dealer code. This information should be included on all communications with the warranty department.
10. Calls to the Warranty Hotline or email system should be used as a last resort, not "The first port of Call". The warranty clerks are happy to help but are not there to act as the dealers warranty administrators.

Richard Wyatt
Manager
Aftersales Technical Support
Sales Operations

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: Level 2A, Mark Oliphant Building
Laffer Drive, Bedford Park
South Australia 5042