WARRANTY INFORMATION BULLETIN

WIB 2007-07 27/06/2007

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Warranty Claim Submissions for Exchange Audio and DVD Units

The MMAL warranty department has seen an increase in odometer discrepancy errors on dealer's warranty claims of late relating to claims submitted for exchange audio and DVD units. This is usually caused by a delay in submitting the warranty claim by the dealer and the warranty claim submitted by the exchange vendor.

Dealers are requested that when a warranty repair is performed for an exchange audio or DVD unit, that the submission of the warranty claim to MMAL occurs within a week of the repair date.

Whilst MMAL allows 30 days from date of repair to date of submission for warranty claims, the delay in not submitting a warranty claim for these particular repairs may result in odometer errors with the dealer's claim and therefore a delay in payment of that claim.

Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039