WARRANTY INFORMATION BULLETIN

WIB 2007-13 18/07/2007

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Rear Seat Entertainment Headphones

After a recent audit by Mitsubishi Motors Corporation (MMC) of Mitsubishi Motors Aust Ltd (MMAL) warranty claims, it was found that some dealers were replacing the original equipment headphone unit with the accessory headphone unit.

MMC have requested that if an original equipment headphone unit fails and is required to be replaced under warranty, then it should be replaced with the original equipment part and claimed as a warranty claim for the first failure and as a parts claim for all subsequent failures. Similarly, if the accessory unit fails and is required to be replaced under warranty, then it should be replaced with the accessory part and claimed as a parts claim.

The two part numbers are shown below and are current at the date of this bulletin:

- 8795A008 - HEADPHONE-AUDIO & VIDEO. This is the original equipment part number.
- MZ360169EX - HEADPHONE-R/SEAT ENTERTAINMENT. This is the accessory part number.

Failure to adhere to this procedure may result in a delay in payment of the warranty claim. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039