WARRANTY INFORMATION BULLETIN

WIB 2008-01 20/02/2008

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Colt Cabriolet Retractable Roof Operation

This Warranty Bulletin is to remind dealers about the use of the Colt Cabriolet retractable roof. If the retractable arms or any other part associated with the retractable roof are broken due to operator error, then this does not constitute a warrantable repair. If there is a manufacturing defect with any part that does not allow the retractable roof to operate as it was designed to, then the part(s) can be replaced under warranty.

There are several MMAL publications that explain how to operate the Colt Cabriolet retractable roof. A list of these publications is shown below:

- Colt Cabriolet owner's manual – Part numbers: OZ8A07E1, OZ8A07E2, OZ8A08E1
- Roof operation quick reference guide – Part number MR936022
- Service Bulletin 00/2006/026 – Subject: 2007 Model Year RZ Colt Cabriolet New Model Introduction
- Retractable Hardtop Operation leaflet – Part Number LZ8A07E1

As a reminder to dealers, the Colt Cabriolet should be delivered to dealerships with the Roof operation quick reference guide hanging from the rear vision mirror. This guide is fitted at port of entry and should be left in the vehicle as a guide to operation.

If a part fails on the retractable arm of the Colt Cabriolet, child parts should be used instead of a complete assembly where applicable. If the child parts are not available, then the warranty claim must be authorised for the use of a complete assembly.

Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039