WARRANTY INFORMATION BULLETIN

WIB 2008-02 20/02/2008

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

NS Pajero Dust Entry

This Warranty Bulletin is to remind dealers about the dust entry kit available for NM and NP Pajero models. This dust entry kit, part number MN167999, is available for NM and NP Pajero models only.

Therefore, if a problem with dust entry is found on NS Pajero, then this should be reported to the relevant departments for the appropriate corrective action. The NM/NP Pajero dust entry kit is not to be used on NS Pajero models.

Failure to adhere to this requirement may result in a warranty claim not being paid, or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039