WARRANTY INFORMATION BULLETIN

WIB 2008-18 27/11/2008

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Recall Notification Advice for Recall 010041

A revised edition of recall notification 010041 was published on the dealer extranet on Friday 31st October 2008 and email notification of the change was announced to the dealer network on Monday 3rd November 2008.

In this revised edition there is a requirement for dealers to send photos as proof of rectification when a work code 20 repair is performed as part of the recall campaign. The additional paragraph added to the recall notification advice is as follows:

Should a vehicle require rectification then a digital photo is required as supporting documentation.
E-mail photograph to goodwill@mmal.com.au using " Recall number – VIN number" in the subject line.
Example ---"010041 – 6MMDB4H416T017724"

Claims submitted for the inspection and repair procedure (work code 20) for this recall that are not accompanied by supporting photos will be put in to RFC status with error messages advising photos are required. Dealers will need to resubmit the applicable claim once photos have been sent to the above email address for the claim to be rejudged.

Failure to adhere to the above requirements may result in a claim not being paid, or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039