MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2008-19 9/12/2008

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Revised Process For Claiming Exchange Audio Units

A revised process for claiming exchange audio units is to become effective immediately.

1. If an exchange audio unit is required, then perform a VIN check in Deacon to locate the audio unit serial number. If the serial number is available using this procedure, then order the exchange unit as usual and when putting in the warranty claim, use the cause part XAUDIO and the labour operation and labour time as reported in WIS (This procedure has not changed).

2. If an exchange audio unit is required and a VIN check in Deacon reveals no serial number, then the audio unit will need to be removed to locate the serial number on the audio unit. After recording the serial number, refit the audio unit and order the replacement exchange audio unit as usual.

   A screen dump of the Deacon screen will need to be attached to the repair order for audit purposes.

   - A warranty claim may be submitted for obtaining the failed audio unit serial number. The cause part for this process is XAUDIO1 and the labour operation and labour time is as advised in WIS.
   - When the exchange unit is replaced a second warranty claim may be submitted for the replacement of the exchange audio unit. The cause part for this process is XAUDIO2 and the labour operation and labour time is as advised in WIS.

Please note that for all of these scenarios, the value of XAUDIO, XAUDIO1 and XAUDIO2 is zero dollars ($0.00), and the repair dates will be the date the repair was completed or the date the serial number was recorded when using the XAUDIO1 scenario.

Failure to adhere to the above requirements may result in a claim not being paid, or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039