WARRANTY INFORMATION BULLETIN

WIB 2008-21 12/12/2008

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Revision to Recall Notification 010042

This bulletin is to be used in conjunction with the revised recall notification 010042 dated 10th December 2008.

Please be advised that there has been a changed made to the recall notification 010042.

In previous correspondence, repair procedures with work code 15, 17 and 19 allowed a $10.00 handling charge. This was an error on MMAL's behalf.

Effective immediately, the handling charge has been removed from the above repair procedures and will not be accepted if the submission date and repair date is after the date of this bulletin. Claims previously submitted with a repair date and submission date prior to the date of this bulletin will be honoured.

Failure to adhere to the above requirements may result in a claim not being paid, or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039