WARRANTY INFORMATION BULLETIN

WIB 2009-01 17/03/2009

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

This bulletin supersedes WIB 2006-12, WIB 2006-12 Revision 1 and WIB 2006-12 Revision 2.

REPAIRED as the Causal Part

This bulletin is to advise of the change in procedure when submitting a warranty, parts or arrival claim (claim type 'W', 'P' or 'A') when the causal part has been repaired and not replaced.

This new procedure is effective from Wednesday 18th March 2009 claim submissions. Claims submitted on or after this date must adhere to this procedure.

This procedure does not apply to campaign claims (claim type 'S') and dealers should always refer to the campaign notification on how to claim for a campaign.

CURRENT PROCESS

The part number REPAIRED is used as the causal part (for zero dollars) and if required, any additional part numbers required to complete the repair are also listed in the Parts section of the claim. Labour used to complete the repair is then claimed in the Labour section of the claim. This part of the process has not changed, although in order to recover costs from suppliers' additional information in a specific format is required.

REVISED PROCESS

In addition to the above process, dealers are required to put in to the Remarks section of the claim the word REPAIRED and then a space and then the MMAL part number of the causal part that was repaired. The word REPAIRED must begin at the first character on the first line of the Remarks section. This information must be put on the first line only and no other remarks must be put on this line. Do not add in additional spaces or additional characters such as -, *, / etc.

Please see the screen shot examples of a WIS claim submission below on how this new procedure should look. (Please note that the details of the example are for illustration purposes only and are not an actual repair).

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039

Labour screen



Part screen



Remarks screen



Warranty claims submitted for this type of repair that do not adhere to this format may be put in to RFC status for dealer correction. (Note that any alterations to the remarks section of the claim will require a resubmission of the entire claim).

To contact Warranty Payments Administration:

Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
E-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039

Failure to adhere to the above requirements may result in a claim not being paid, or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039