MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2010-03 10/06/2010

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

CJ Lancer Rear Centre Seat Belt Replacement

This Warranty Bulletin is to advise dealers that effective from the date of this bulletin the times for replacing the rear centre seat belt on CJ Lancer are as follows:

Sedan

Position Code	Work Code	Operation Time
522081	10	0.3 hours

Sportsback (Hatch)

Position Code	Work Code	Operation Time
522081	H1	0.8 hours

These times are correct as at the date of this bulletin and may change in the future. The operation code and time for the Sportsback is not in the current version of WIS, but will be added to future versions of the WIS. Please check future WIS versions for up to date operation times.

Dealers should check that the operation code and time being claimed is relevant to the model from which the seat belt was replaced.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:

Warranty Telephone: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039