MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2011-01 10/01/2011

This Bulletin forms part of the Warranty Procedure Manual.


ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Triton Canopy Replacements

This Warranty Bulletin is to advise dealers of the change in procedure when claiming for a replacement or repaired canopy on ML and MN Triton models.

MMAL require dealers to enter the failed canopy serial number, replacement canopy serial number and failed canopy part number in the remarks section of the claim when the canopy is replaced. Below is a screen shot from WIS to show how the remarks section of the claim should look for the replacement of a failed canopy. It is mandatory that these fields are completed on the claim as they are shown. (Serial numbers and part numbers used in the screen shot are examples only).

Canopy Replacement



1. Type FAILED CANOPY SERIAL on the first line of the remarks (XA line), leave 1 space and then type the failed canopy serial number. (Serial number 095854 has been used as an example in the above screen shot).
2. Type REPLACE CANOPY SERIAL on the second line of the remarks (XB), leave 1 space and then type the replacement canopy serial number. (Serial number 102137 has been used as an example in the above screen shot).
3. Type FAILED CANOPY PART on the third line of the remarks (XC line), leave 1 space and then type the failed canopy part number. (Part number M314280T64 has been used as an example in the above screen shot).
4. From the fourth line onward (XD line), type any free text that may be relevant to support the claim including any hotline fix references if applicable.


The repaired canopy part number and the repaired canopy serial number are required in the remarks section of the claim if the canopy is repaired. Below is a screen shot from WIS to show how the remarks section of the claim should look for the repair of a failed canopy. It is mandatory

To contact Warranty Payments Administration:

Warranty Telephone:	(08) 8275 2367	**e-mail:**	warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Fax:	(08) 8275 2496	**Address:**	1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039

that these fields are completed on the claim as they are shown.

Canopy Repair



1. Type REPAIRED on the first line of the remarks (XA line), leave 1 space and then type the part number of the repaired canopy. (Part number M314279W32 has been used as an example in the above screen shot).
2. Type REPAIRED CANOPY SERIAL on the second line of the remarks (XB line), leave 1 space and type the repaired canopy serial number. (Serial number 102137 has been used as an example in the above screen shot).
3. From the third line onward (XC line), type any free text that may be relevant to support the claim including any hotline fix references if applicable.

Please see below, Figure 1 - a photo of the canopy data label which contains the MMAL part number and canopy serial number, Figure 2 - a photo of where the canopy data label is located on the canopy and Figure 3 – a close up photo of where the canopy data label is located on the canopy.




Figure 1.

To contact Warranty Payments Administration:

Telephone Warranty Hot Line: (08) 8275 2367

Fax: (08) 8275 2496

E-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au

Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039



Figure 2.




Figure 3.

Dealers must also send a photo of the data label on the failed canopy and at least 1 photo that indicates a fault with the canopy. The photo of the data label must clearly show the serial number and MMAL part number. All photos must be of sufficient clarity to clearly identify the data label and the fault with the canopy and should be resized to allow ease of storage and email transmission. Photos should be emailed to MMAL Warranty at the email address: warrantyadmin@mmal.com.au The email that is sent with the photos must also contain the VIN from which the faulty canopy was replaced/repaired.


To contact Warranty Payments Administration:

Warranty Telephone:	(08) 8275 2367	**e-mail:**	warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Fax:	(08) 8275 2496	**Address:**	1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039

Dealers should note that all claims submitted for canopy replacements or canopy repairs must be claimed as a parts claim (claim type ‘P’).

This new procedure is applicable as at the date of this bulletin. Any claims with a repair date on or after the date on this bulletin must adhere to these requirements.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.



Ian K. Matthews
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:

Telephone Warranty Hot Line:	(08) 8275 2367	**E-mail:**	warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Fax:	(08) 8275 2496	**Address:**	1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039