MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2011-04 01/07/2011

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Diagnostic Trouble Codes

This Warranty Bulletin is to advise dealers that effective from the date of this warranty bulletin, any diagnostic trouble codes, test results or before and after measurements or readings that are recorded on a repair order, must also be recorded in the remarks section of the warranty claim.

As per the Service Procedure Manual, section 21.1.12, the above mentioned recordings must be documented on the repair order. Effective from the date of this warranty bulletin, these recordings must also be recorded in the remarks section of the warranty claim.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:

Warranty Telephone: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039