MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2011-05 27/07/2011

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Triton Canopy Destruction Procedure

Effective immediately, Triton canopies with part numbers listed below can be destroyed as early as 30 days after the warranty claim payment date except when MMAL has requested the canopy to be retained longer. Requests for longer retention may be made by telephone or email. All requests will be confirmed via email. Emails will be signed by the undersigned.

This procedure replaces the standard 90 day holding procedure detailed in the Warranty Procedure Manual and General Letter GL - 07- 032 for the part numbers listed below where "*xnn*" represents the colour option e.g. M314277A02.

Part Number	Description
M314277*xnn*	**CANOPY,HIGH,SLIDE**
M314279*xnn*	**CANOPY,TRADE**
M314280*xnn*	**CANOPY,SPORTS**
M350020*xnn*	**CANOPY,TRADE,W/TILT UP**
M350021*xnn*	**CANOPY,HIGH,TILT**

This change is only applicable to the Triton canopies listed in this bulletin.
All other parts must continue to be held for 90 days from warranty claim payment date.

Dealers must ensure that all requirements outlined in warranty bulletin **WIB-2011-01** have been carried out prior to the destruction of the canopy, including sending the relevant photos and claim details.

Failure to adhere to the above requirements may result in a claim not being paid, or the claim reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:
Warranty Telephone: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039