MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2012-01 13/01/2012

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

380 Window Regulators – Cancelled Bulletin

This Warranty Bulletin is to advise dealers that the Warranty Bulletin WIB-2010-09 dated 17/12/2010 has been cancelled.

It is no longer a requirement for dealers to continue to hold all failed 380 window regulators beyond the mandatory 90 day hold period (90 days from claim payment date). All dealership Service Managers should have received a letter from MMAL Warranty with instructions on what to do with the failed 380 window regulators that have been held by dealerships.

If a letter has not been received by the dealership Service Manager, please contact the MMAL Warranty department immediately.

MMAL Warranty would like to advise that the investigation is now complete and would like to thank all dealerships for their cooperation with this request.

Ian K. Matthews
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:

Warranty Telephone:	(08) 8275 2367	**e-mail:**	warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Fax:	(08) 8275 2496	**Address:**	1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039