MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2012-12 19/09/2012

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Use of Work Code 99

This Warranty Bulletin is to remind dealers on the use of work code 99 and when it should or should not be used.

Dealers can use a 99 work code when:
1. The position code in WIS is a Quality Information Position Code Only or
2. If the operation code (position code and work code combination) is not recognised when trying to submit a claim to SAP (this is only a temporary solution until the issue is resolved).

As per the Warranty and Service Procedure manuals, the time claimed when using a 99 work code must be supported by technician clocking times. If a 99 work code is used for point 2 above and an operation time is published, the time claimed on the 99 work code must not exceed the published time. Dealers must make comments in the remarks section of the claim if a 99 work code is used and if point 2 above is used Dealers are requested to put the position code and work code combination that could not be saved in SAP.

Dealers are also reminded that when claiming for recall and service campaign claims they must submit the claim exactly as the recall or service campaign notification advises. Unless the recall or service campaign notification advises to use a 99 (or LT) work code in the claim, then these codes must not be used.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Neale Clarke
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:
Warranty Telephone: (08) 8275 2367
e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039