MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2012-15 9/10/2012
Revised
18/3/2015

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Part Return – Fuel Injectors and Fuel Pumps

Effective from the revision date of this bulletin, MMAL Service Department no longer require the return of defective parts outlined in the below bulletin.

This bulletin is now closed.

Until further notice, MMAL's Service department require the return of a select number of failed parts as advised below.

If any of the following part numbers have failed and are replaced under warranty, please return the parts to MMAL using the following instructions.

1. Ensure each part is correctly "tagged" with vehicle information such as VIN, Repair Date, Repair Odometer, Symptom and Cause and Claim Number.
2. Package the part(s) to prevent damage. Refer WIB-2005-08 (use original packaging where possible).
3. Contact TNT on: Phone 131150. Request "Overnight First Class". Use the TNT Account No 21628821 (Ref Only: Ceva Logistics MMAL A/C). Request the driver to bring a consignment note. In the "Your Ref No" field write - "MWTY".
4. Address the consignment note as follows:
   Mitsubishi Motors Australia Ltd.
   1284 South Road,
   Clovelly Park, SA 5042
   Attention: Service Department

The part numbers that are requested for return are as follows:

1465A041 - Fuel injector
1465A279 - Fuel injector
1465A257 - Fuel injector
1465A054 - Fuel injector
1465A297 - Fuel injector

1460A044 - Fuel pump
1460A053 - Fuel pump
1460A040 - Fuel pump
1460A047 - Fuel pump
1460A019 - Fuel pump
1460A003 - Fuel pump
1460A022 - Fuel pump
1460A059 - Fuel pump

Neale Clarke
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:
Warranty Telephone (08) 8275 2367
E-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039