WARRANTY INFORMATION BULLETIN

WIB 2013-17 13/09/2013

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

Clarification of Brake Disc Rotor Replacement/Machining

It has been brought to our attention that information provided in Warranty Training sessions since the release of the Service Procedure Manual dated July 2011 is incorrect.

The Warranty training sessions may have mentioned General Letter GL-06-023 with regard to the above subject. This General Letter has been superseded by MMAL's Service Procedure Manual. Please refer to section 18.1.15 - Consumable Parts, of the Service Procedure Manual for details of the correct policy.



Ian Matthews
Manager, Warranty Systems and Claim Administration
National Service

To contact Warranty Payments Administration:
Warranty Telephone: (08) 8275 2367

e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039