WARRANTY INFORMATION BULLETIN

WIB 2013-21 05/11/2013

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

SRS Part Replacement and Collection - Update

MMAL Warranty wish to advise that the collection and return of SRS parts outlined in Warranty Information Bulletin WIB-2013-16 is no longer required.

Warranty Information Bulletin WIB-2013-16 has been marked as cancelled to reflect this change in procedure.



Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Warranty Telephone: (08) 8275 2367

e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039