MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2013-27 29/11/2013

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

Update to Hotline Fix MN52-001 and PB52-001

MMAL's Service department are currently in the process of updating the above subject hotline fixes which will result in a change to some of the operation codes and operation times which must be used.

Any claims submitted using the revised operation codes and times from these hotline fixes MUST be submitted using the new portal submission system and not WIS. These codes and times will not be loaded in WIS which is why the portal submission system must be used.

The operation codes and times (subject to change) are as follows:

MN52-001 – Triton

CODE	W/G	DESCRIPTION	TIME
543544 H1	01/01	ROOF HARNESS … SRS CHECKING	0.4
543545 H1	01/01	FLOOR HARNESS … SRS CHECKING	0.4
543545 10	01/01	FLOOR HARNESS … REPLACEMENT	1.2
		[Incl.] Floor console assembly - R&I	
		Seat assembly - R&I	
		Floor carpet (mat) - R&I	
		[Additional operation]	
		B2 … Double cab (tandem)	0.9
		F3 … Club cab	0.3
		A9 … Inspection by multi-use tester	0.2
543544 10	01/01	ROOF HARNESS … REPLACEMENT	0.5
		[Incl.] Headlining assembly - R&I	
		[Additional time allowance]	
		F2 … Double cab (tandem)	0.9
		F3 … Club cab	0.4
		[Additional operation]	
		A1 … Rear seat back - R&I (for club cab)	0.2
		A9 … Inspection by multi-use tester	0.2

To contact Warranty Payments Administration:
Warranty Telephone: (08) 8275 2367
e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039

PB52-001 – Challenger

CODE	W/G	DESCRIPTION	TIME
543543 H1	01/01	BODY (REAR) HARNESS (WIRING HARNESS C) … SRS CHECKING	0.4
543544 H1	01/01	ROOF HARNESS … SRS CHECKING	0.4
543543 10	01/01	BODY (REAR) HARNESS (WIRING HARNESS C) … REPLACEMENT	4.1
		[Incl.] Floor console assembly - R&I Seat assembly - R&I Floor carpet (mat) - R&I	
		[Additional operation]	
		A1 … Third seat - R&I	0.7
		A9 … Inspection by multi-use tester	0.2
543544 10	01/01	ROOF HARNESS … REPLACEMENT	1.9
		[Incl.] Headlining assembly - R&I	
		[Additional operation]	
		A3 … Curtain air bag module - R&I	0.3
		A9 … Inspection by multi-use tester	0.2

Dealers must only use the operation codes that are applicable to the DTC that has been logged and must not use a 99 work code.



Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
E-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039