MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB-2014-07 18/06/2014

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

VSR OVER1800 has been renamed to be OVERLIMIT

VSR OVER1800 has been renamed to be OVERLIMIT.

This change is effective as of 18/6/2014.

The VSR considers any of the following claim types ZC01, ZC04, ZC06.

Refer to General Letter GL-14-012 for the specified limit.

The message displays as **OVERLIMIT:Not to Procedure** and places the claim in ZRFC

Changes have been made to the validation and it now performs as follows.

The VSR will display where:-

1. Any individual claim exceeds the specified limit.

2. Any group of claims exceeds the specified limit, where multiple claims for repairs on the same day are submitted, claims will be grouped based on Major Group (first 2 characters of Quality Position code)

If the total claimed value for any Major Group exceeds the specified limit, then ALL (but only) these claims will display the VSR error.
eg a vehicle has four claims all individually below the limit, two are from the same Major Group, resulting in the total for the Major Group exceeding the limit, only these two claims will display the VSR message.

Where claims are failed based on Point 2 **ALL CLAIMS** identified require an SCA.
ie. where two claims are received with quality coding **eg. 35**2620 and **35**2220 and the total of the claims exceeds the limit, if only one claim is authorised, regardless of value, the other claim will still error with VSR OVERLIMIT.

Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Warranty Telephone: (08) 8275 6528

e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au

Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039