WARRANTY INFORMATION BULLETIN

WIB 2014-19 05/11/2014

This Bulletin forms part of the Warranty Procedure Manual.

This Bulletin relates to Service Campaign 020116 4D56 Hi-Power Overheat –Working procedure

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

PLEASE NOTE:- Claims for campaign 020116 which have not been created via the "WARRANTY APPLICATION'" will be reversed.

Please follow the steps on the warranty application provided.

Save the file created to your desktop or an appropriate file location on your computer. Then use the saved file to create the claim on the SAP Portal.

Manual entry of campaign 020116 claims **WILL LEAD** to your claim being reversed.



Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:

Warranty Telephone: 1300130099 option 2 option 4

e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au

Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039