MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2015-02 3/02/2015
Revised
13/03/2015

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

New Operation Codes for Triton and Challenger Long Engine Replacement

Dealers are advised that the following operation codes must be used for Long Engine Assembly - Replacement on Triton and Challenger.

These codes are to be used only for Long Engine Assembly - Replacement.
Continue to use Engine Assembly - Replacement as shown in the V1.0 of the Operation Code Manual where a complete Engine Assembly has been fitted.

Triton (ML/MN)

Code	Work Group	Description
110012 10	P1/P1	LONG ENGINE ASSEMBLY … REPLACEMENT
		[Additional time allowance as required]
		C3 … With air-conditioner
		C8 … Automatic transmission
		G6 … DOHC engine
		M6 … Automatic transmission, With transfer
		Q8 … Manual transmission, With transfer
		[Additional operation]
		AA … Rear heater air duct - R&I

Challenger (PB)

Code	Work Group	Description
110012 10	P1/P1	LONG ENGINE ASSEMBLY … REPLACEMENT
		[Additional time allowance as required]
		M6 … Automatic transmission, With transfer
		Q8 … Manual transmission, With transfer
		[Additional operation]
		AA … Rear heater air duct - R&I

Times for these codes have been loaded and are effective September 2014.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Warranty Telephone: 1300130099 option 2
option 4
e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039